



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388



LKK.
Meng Yan.

ESTIMATE

Account Details			Account No.		Customer Details		
Allianz Insurance Singapore Pte Ltd 12 Marina View #14-01 Asia Square Tower 2 Singapore 018961			S1000040 / ALLIANZ		Mr Wong Jun Hong 612 Clementi West Street 1 #06-326 Singapore 120612 Mobile: 96827483		
			Document No. 0				
			Document Date 14/04/2023				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ASE30R	AEZLZQ F5	25/04/2019	SMK0075Y	0	22469	61TP/SMK0075Y/130423
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTHBA1D2505095969		8ARZ158220	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES T/P INS: ALLIANZ ACC DATE: 13.04.2023 T/P VEH: SMT5238P DATE IN: DATE SURVEY: DATE AUTHORIZE:				50	100.00
2	B	BP-LAB3 TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON REAR BUMPER, REAR PANEL, BOOT COVER AND FIX NEW PARTS				1920	4800.00
3	B	BP-RES3 TO SPRAY PAINT ON WHOLE REAR AFFECTED PORTION OF VEHICLE (SPECIAL PAINT - PER PANEL - \$1224)				2448 / 3672	6936.00
4	B	BP-LAB3 TO REMOVE AND RE-INSTALL REAR LUGGAGE TRIM, GARNISH ETC TO ENABLE REPAIR (NETT)					480.00
5	B	BP-LAB3 TO REMOVE AND TRANSFER REAR SENSOR TO NEW BUMPER, REPLACE IF DAMAGE (NETT)					240.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388



ESTIMATE

Account Details			Account No.		Customer Details		
Allianz Insurance Singapore Pte Ltd 12 Marina View #14-01 Asia Square Tower 2 Singapore 018961			S1000040 / ALLIANZ		Mr Wong Jun Hong 612 Clementi West Street 1 #06-326 Singapore 120612 Mobile: 96827483		
			Document No. 0				
			Document Date 14/04/2023				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ASE30R	AEZLZQ F5	25/04/2019	SMK0075Y	0	22469	61TP/SMK0075Y/130423
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTHBA1D2505095969		8ARZ158220	60	Carine Yeo C L	--/--/----		0.00 --/--/----
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
6	B	BP-LAB3 TO CHECK WIRING AND LIGHTS FUNCTIONING AND CARRY OUT WATER LEAK TEST (NETT)					240.00
7	B	BP-LAB3 TO REMOVE AND TRANSFER REAR REVERSE CAMERA TO NEW BOOT (NETT)					240.00
8	B	BP-LAB3 TO REMOVE AND TRANSFER BOOT COMPONENT AND MECHANISM TO NEW BOOT (NETT)					480.00
9	Z	BP-SLANT SUPPLY BOOT SEALANT (NETT)					100.00
10	Z	BP-SLANT SUPPLY REAR PANEL SEALANT (NETT)					100.00
11	B	BP-ECU3 TO RESET ECU AND REPROGRAMME (NETT)					240.00
12	T	BP-MISC1 SHOULD THE ABOVE VEHICLE BE SUBJECT TO TOTAL LOSS OR TOW OUT BY INSURANCE COMPANY OR BY THE OWNER PRIOR TO THE REPAIR A 6% OF THE QUOTATION PRICE WILL BE IMPOSED AS ADMIN CHARGES TO A MAX OF \$1000 + TOWING CHARGES IF APPLICABLE.					
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388



ESTIMATE

Account Details	Account No.	Customer Details
Allianz Insurance Singapore Pte Ltd 12 Marina View #14-01 Asia Square Tower 2 Singapore 018961	S1000040 / ALLIANZ	Mr Wong Jun Hong 612 Clementi West Street 1 #06-326 Singapore 120612 Mobile: 96827483
	Document No. 0	
	Document Date 14/04/2023	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ASE30R	AEZLZQ F5	25/04/2019	SMK0075Y	0	22469	61TP/SMK0075Y/130423
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTHBA1D2505095969	8ARZ158220	60	Carine Yeo C L	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	Z	BP-MISC2 A DAILY STORAGE CHARGE AT THE RATE OF S\$25/- PER DAY WILL COMMENCE 7 DAYS AFTER ESTIMATE DATE. THESE CHGS WILL NOT APPLY IF REPAIRS ARE UNDERTAKEN BY BORNEO MOTORS.				
14	1	L52159-53947 COVER, RR BUMPER <i>ca</i>	1.00	1278.70		1278.70 ✓
15	2	L52169-53060 COVER, RR BUMPER, <i>? xan</i>	1.00	606.20		606.20 ✓
16	3	L52161-53090 PIECE, RR BUMPER <i>ca</i>	1.00	39.10		39.10 ✓
17	4	S52161-0K040 PIECE, RR BUMPER <i>ca</i>	6.00	4.90		29.40 ✓
18	5	L52158-53070 SUPPORT, RR BUMPER <i>? xan</i>	1.00	172.40		172.40 ✓
19	6	L52157-53070 SUPPORT, RR BUMPER <i>? xan</i>	1.00	172.40		172.40 ✓
20	7	L52156-53040 SUPPORT, RR BUMPER <i>? xan</i>	1.00	291.00		291.00 ✓
21	8	L52155-53070 SUPPORT, RR BUMPER <i>? xan</i>	1.00	291.00		291.00 ✓
22	9	L52023-53100 REINFORCEMENT <i>? ca</i>	1.00	571.60		571.60 ✓
23	0	L52615-53150 ABSORBER, RR BUMPER <i>? ca</i>	1.00	134.40		134.40 ✓
24	1	L52198-53020 BRACKET, RR BUMPER <i>ca</i>	1.00	5.90		5.90 ✓
25	2	L52197-53040 BRACKET, RR BUMPER <i>ca</i>	1.00	5.90		5.90 ✓
26	3	L58307-53100 PANEL SUB-ASSY, BODY <i>? xan</i>	1.00	981.20		981.20 ✓
27	4	L58390-53012 COVER ASSY, FLOOR <i>? xan</i>	1.00	606.20		606.20 ✓
28	5	L64716-53100 C1 COVER, LUGGAGE <i>? xan</i>	1.00	382.00		382.00 ✓

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388



ESTIMATE

Account Details			Account No.		Customer Details			
Allianz Insurance Singapore Pte Ltd 12 Marina View #14-01 Asia Square Tower 2 Singapore 018961			S1000040 / ALLIANZ		Mr Wong Jun Hong 612 Clementi West Street 1 #06-326 Singapore 120612 Mobile: 96827483			
			Document No. 0					
			Document Date 14/04/2023					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	ASE30R	AEZLZQ F5	25/04/2019	SMK0075Y	0	22469	61TP/SMK0075Y/130423	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTHBA1D2505095969		8ARZ158220	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
29	6	L64401-53301	PANEL SUB-ASSY	1.00	944.80		944.80	
30	7	L64461-53030	WEATHERSTRIP	1.00	285.90		285.90	
31	8	L90975-02078	EMBLEM, SYMBOL	1.00	86.20		86.20	
32	9	L75443-53330	PLATE, LUGGAGE COMPT	1.00	82.00		82.00	
33	0	L75441-53110	PLATE, LUGGAGE COMPT	1.00	82.00		82.00	
34	1	L89341-78010 J3	SENSOR, ULTRASONIC	2.00	546.10		1092.20	
35	2	L52563-53030	RETAINER, RR BUMPER	1.00	150.80		150.80	
36	3	L52562-53030	RETAINER, RR BUMPER	1.00	150.80		150.80	
37	4	L81498-53010	COVER, RR	1.00	44.90		44.90	
38	5	L81497-53010	COVER, RR	1.00	44.90		44.90	
39	6	L89997-30100	ANTENNA, ELECTRICAL	1.00	86.70		86.70	
40	7	L81590-53161	LAMP ASSY, RR, LH	1.00	851.60		851.60	
41	8	L81561-53311	LENS & BODY, RR	1.00	1524.50		1524.50	
42	9	L81496-60010	GUIDE, RR	2.00	4.30		8.60	

Panel
Hp 900100 CS
7 days
17/01/23 @ 1550
Resny before
paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer
Signature: _____
Date: _____

For & on behalf of Borneo Motors (Singapore) Pte Ltd Signature: _____ Date: _____	Customer's Signature	Charge Summary	Total	24,959.30	
			GST 8.00%	1,996.74	
		Parts	11,003.30		
		Labour	13,956.00		
		Sublet	0.00		
	Lubrication/Fluid	0.00	Less	0.00	
	Others	0.00	Amount Due	26,956.04	

Customer Copy