

### SERVICE ESTIMATE

##### - C00001      SL: SERVICE SALES - PC

Mrs Vetkazova  
27 West Coast Rise

04-09  
Singapore 127470

Closed by .... : Paul Ong Qing Yong  
Svc Consultant :  
Remarks ..... : Mrs Natalia Vetkazov

GST Reg.No:M28920628X

Inv.No. . . : B&P                      0    Page 1  
Inv.date. . : 12/04/2023  
WIP No. . . : 15769  
Veh.In/Out:  
\*Tel.No. . . : Home: 97843652  
Reg.No. . . : SNH9721K  
Reg.date . . : 28/11/2018  
Mileage .. :                      0  
Chassis No: SJKDDAH15U2000630

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, LOWER BUMPER, REAR TAILGATE, BUMPER BEAM, TAILLAMP	0	3200.00	0		3,200.00	S
800	TO SPRAYPAINT ON REAR BUMPER, LOWER BUMPER, REAR TAILGATE	0	3200.00	0		3,200.00	S
802	TO REMOVE, REFIT & TRANSFER REAR TAILGATE COMPONENTS	0	400.00	0		400.00	S
802	TO REPLACE REAR WINDSCREEN	0	800.00	0		800.00	S
0080	TO INSTALL REAR WINDSCREEN FIL	0	280.00	0		280.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	621.00	0		621.00	S
R06	NUMBER PLATE & HOLDER	0	120.00	0		120.00	S
	BUMPER SET-RR Q30	1.0 EA	3056.80			3,056.80	S
	BUMPER RR LOWER MOUL	1.0 EA	1261.00			1,261.00	S
	REINFORCEMENT-BUMPER	1.0 EA	2167.70			2,167.70	S

### SERVICE ESTIMATE

##### - C00001      SL: SERVICE SALES - PC

Mrs Vetkazova  
27 West Coast Rise

04-09  
Singapore 127470

Closed by .... : Paul Ong Qing Yong  
Svc Consultant :  
Remarks ..... : Mrs Natalia Vetkazov

GST Reg.No:M28920628X  
Inv.No. . . : B&P                    0    Page 2  
Inv.date. . : 12/04/2023  
WIP No. . . : 15769  
Veh.In/Out:  
\*Tel.No. . . : Home: 97843652  
Reg.No. . . : SNH9721K  
Reg.date . . : 28/11/2018  
Mileage .. : 0  
Chassis No: SJKDDAH15U2000630

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	RETAINER-BUMPER Q30	1.0 EA	580.40			580.40	S
	FINISHER-REAR B LH	1.0 EA	223.70			223.70	S
	FINISHER-REAR B RH	1.0 EA	252.50			252.50	S
	DIFFUSER ASSY LH	1.0 EA	410.10			410.10	S
	DIFFUSER ASSY RH	1.0 EA	410.10			410.10	S
	RETAINER LH-RR BUMPE	1.0 EA	126.40			126.40	S
	RETAINER RH-RR BUMPE	1.0 EA	126.40			126.40	S
	TAILGATE Q30	1.0 EA	8740.00			8,740.00	S
	FINISHER TAILGATE OU	1.0 EA	1160.30			1,160.30	S
	FINISHER ASSY CHROME	1.0 EA	4819.30			4,819.30	S
	WINDSCREEN RR TAILGA	1.0 EA	5990.20			5,990.20	S
	EMBLEM-BACK DOOR	1.0 EA	119.90			119.90	S
	ORNAMENT-BACK DOOR	1.0 EA	147.50			147.50	S
	HARNESS-SUB,REA	1.0 EA	298.80			298.80	S
	REFLECTER LAMP REAR	1.0 EA	120.50			120.50	S
	REFLECTER LAMP REAR	1.0 EA	120.50			120.50	S
	TAILAMP REAR,LH Q30	1.0 EA	1814.10			1,814.10	S

### SERVICE ESTIMATE

##### - C00001      SL: SERVICE SALES - PC

Mrs Vetkazova  
27 West Coast Rise

04-09  
Singapore 127470

Closed by .... : Paul Ong Qing Yong  
Svc Consultant :  
Remarks ..... : Mrs Natalia Vetkazov

GST Reg.No:M28920628X

Inv.No. . . : B&P                    0    Page 3  
Inv.date. . : 12/04/2023  
WIP No. . . : 15769  
Veh.In/Out:  
\*Tel.No. . . : Home: 97843652  
Reg.No. . . : SNH9721K  
Reg.date . . : 28/11/2018  
Mileage .. : 0  
Chassis No: SJKDDAH15U2000630

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	COVER SONAR SENSOR F	2.0 EA	105.80			211.60	S
	COVER SONAR RR OUTER	2.0 EA	105.80			211.60	S
	*D* PRIMER GLASS & P	1.0 EA	46.90			46.90	S
	SEALANT WINDSCREEN	2.0 EA	192.90			385.80	S

	Gross Total.	41,423.10
<b>Labour Total</b>	8,621.00	Net..... 41,423.10
<b>Parts Total</b>	32,802.10	GST @ 8.0% 3,313.85
<b>Package Total</b>	0.00	Total..... 44,736.95
		Paid..... 0.00
		Please Pay.. 44,736.95

GST: S=StdRated; O=OutOfScope; Z=ZeroRated; P=PreviousRate