



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Ref: CS/AGI23003946/Uny3e2

Date: 02/05/2023

Code: AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKX 3563R	Veh. Inspected	SND 1721J
Policy No.	P10030302R05	Coverage (\$)	0.00
Claim No.	C10021674/SR	Excess (\$)	0.00
Assign From	DON BONG	Assign Date	17/04/2023

2. Vehicle Particulars & Condition

Make & Model	TOYOTA C-HR HYBRID (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	ZYX102117677	Colour	SILVER
Odometer	103945 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R17	MICHELIN	6 mm
L/H Front Tyre	215/60 R17	MICHELIN	6 mm
R/H Rear Tyre	215/60 R17	MICHELIN	6 mm
L/H Rear Tyre	215/60 R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/04/2023	Inspection Date	24/04/2023
Survey held at	KAIZEN MOTORS (ENGINEERING) PTE LTD 68 KAKI BUKIT AVENUE 6 #02-12 ARK@KB SINGAPORE 417896		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**