



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

REPAIR PERFORMA INVOICE

bizSAFE
S T A R



Vehicle number	SML5915K
Make / Model	MITSUBISHI ATTRAGE
Chassis number	MMBSTA13AKH001867
Accident date	16/4/23
Reference	2304-24

Qty Particulars

Unit Price - SGD \$

<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER	708 814.20 DMC
2	REAR BUMPER SIDE RETAINER	59.80 ? X
2	REAR BUMPER REFLECTOR L/H	52 96.00 X SCR
1	REAR BUMPER LOWER GARNISH	✓ 419.30 X BT
2	REAR BUMPER BRACKET	318.20 ? X
1	END PANEL	562.30 ? R
1	END PANEL KEYLESS SENSOR	✓ 110.00 ? BRC
1	END PANEL TOP GARNISH	104.74 ? X
1	TAILLAMP L/H	277 317.40 DRC
1	TAILLAMP SEALER	✓ 20.00 NEC
1	REAR FENDER INNER TRIM	363.40 X
1	REAR FENDER	832.25 R
1	BOOTLID	953.30 R
1	BOOTLID WEATHERSTRIP	170.00 X
1	BOOTLID EMBLEM	✓ 47.15 NEC
1	BOOTLID EMBLEM -ATTRAGE	✓ 35.30 WEC
1	BOOTLID EMBLEM - MIVEC	✓ 43.60 NEC
1	BOOTLID OUTER GARNISH	✓ 159.30 SCR
1	REAR FENDER AIR VENT	103.50 ? X
1	REAR WINDSCREEN MOULDING	46.00 X
		5575.74 1871.65
Less 20 %		1115.15 374.33
Subtotal		4460.59 1497.32
Balance C/F		4460.59 ✓
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1 SET	REAR BUMPER CLIP	30.00 NEC
1 SET	REAR FENDER INNER TRIM CLIP	30.00 Y
1 SET	REAR REVERSE SENSOR	200.00 DMC/show
1	JOINT SEALANT	150.00 X
1	WINDSCREEN SEALANT	150.00 Y
Subtotal		560.00 230
Balance C/F		5020.59 1727.32 ✓

<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30
2	REMOVE,REFIT REAR LINING, TRIM AND GARNISH	200.00 250
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 140
4	REMOVE AND RENEW REAR WINDSCREEN	150.00 X
5	TRANSFER PARTS, ATTACHMENT FROM BOOTLID TO NEW	150.00 100 X
6	PANEL BEATING ON AFFECTED AREAS	1000.00 600 700
7	SPRAY PAINTING ON AFFECTED AREAS	1000.00 600
8	APPLY ANTI RUST ON AFFECTED AREAS	150.00 X
Subtotal		2860.00 1420
Grand total		7880.59

04 days *fil* LIS
 Akid 8700 5631
 18104123 1737

3147.32
 20%: 629.464
 =2517.856
 ~\$2600.00

akid@LKKauto.com

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: