



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: OH VALE			Ref: CS/HSB23003998/Knp3m4 Date: 09/05/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2911Y	Veh. Inspected	YN 8391Z	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S3M04LP4	Excess (\$)	0.00	
Assign From	OH VALE	Assign Date	18/04/2023	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI CANTER (M)	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	FEB21EA10168	Colour	WHITE	
Odometer	338990 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/85 R15	YOKOHAMA	9 mm	
L/H Front Tyre	195/85 R15	YOKOHAMA	9 mm	
R/H Rear Tyre	195/85 R15 (D)	YOKOHAMA	4/4 mm	
L/H Rear Tyre	195/85 R15 (D)	YOKOHAMA	4/4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/04/2023	Inspection Date	02/05/2023	
Survey held at	SENG HWEE MOTOR BLK 1018, #01-350 YISHUN INDUSTRIAL PARK A SINGAPORE 768760			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		