



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS23004000/Rqp3 Date: 18/04/2023 Code: AIS	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.	Veh. Inspected	YP 1225G	
	Policy No. SP2003732344	Coverage (\$)	0.00	
	Claim No. 202332007252	Excess (\$)	700.00	
	Assign From JANICE KOH	Assign Date	18/04/2023	
2. Vehicle Particulars & Condition				
	Make & Model	c.c	0	
	Engine No. HIDDEN	Year of Reg.		
	Chassis No.	Colour		
	Odometer -	Steering		
	Brakes	Modification		
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date 12/04/2023	Inspection Date	19/04/2023	
	Survey held at 5 SOON LEE STREET #01-55, PIONEER POINT			
	Repairer CHENG AUTO BODYWORKS			
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				