



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR23004007/Rvy3e2	
			Date: 05/05/2023	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMB 5018C	Veh. Inspected	PC 1380R	
Policy No.		Coverage (\$)	0.00	
Claim No.	BUS/04/23/5026	Excess (\$)	0.00	
Assign From	ASHLENE LEE	Assign Date	18/04/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	ISUZU LT134P	c.c	7790	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	JALLT134PB7000002	Colour	MULTI COLOUR	
Odometer	569672 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	11 R22.5	FRONWAY	8 mm	
L/H Front Tyre	11 R22.5	FRONWAY	8 mm	
R/H Rear Tyre	11 R22.5 (D)	FRONWAY	8/8 mm	
L/H Rear Tyre	11 R22.5 (D)	FRONWAY	8/8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	14/04/2023	Inspection Date	20/04/2023	
Survey held at	WOODLANDS TRANSPORT SERVICE PTE. LTD. 8 GUL CIRCLE SINGAPORE 629564			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>1 Working Days</b>	