



## TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

Our Ref : SNB6224E

Yours Ref : 20233200700SL-GK-SNC4689E

### ALLIANZ INSURANCE SINGAPORE PTE LTD

07 June 2023

79, ROBINSON ROAD #09-01  
SINGAPORE 068897

Attn: MOTOR CLAIMS DEPT

Dear Sir / Madam,

RE: ACCIDENT INVOLVING VEHICLE NO.: SNB6224E & SNC4689E ON 04/04/2023 @ 17:45 HRS ALONG PASIR RIS DRIVE 12

The vehicle had been surveyed by your appointed surveyor and repaired to our client's satisfaction.

We hereby submit the details of claim as follow:

Cost of Repair	:	S\$10,270.04
Loss of Use (\$ 150.00 x 6 days)	:	S\$900.00
Additional Loss of Use (\$ 150.00 x 2 days)	:	S\$300.00
GIA / LTA Search	:	S\$26.75
Parts Delay (\$150 x 17days)	:	S\$2,550.00
		<u>S\$14,046.79</u>

Kindly revert within SEVEN days. Filling which we reverse our rights to refer the matter to our solicitors.

Your kind attention to the matter would be much appreciated.

Yours faithfully,

  
TONG LUCK AUTO PTE LTD

## AUTHORISATION LETTER

I, MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE PTE LTD, owner of SNB6224E hereby authorize TONG LUCK AUTO PTE LTD to act for me with my respect to our claim for repair costs and/or rental and/or loss of use for our vehicle no.: SNB6224E that was damaged pursuant to the accident which occurred on 04/04/2023 ALONG PASIR RIS DRIVE 12 involving vehicle nos: SNC4689E & SGT2302C

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the

Dated this 7th day of June 2023




*Handwritten signature*

Signed by third party claimant



*Handwritten signature*  
TONG LUCK AUTO PTE LTD



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

## TAX INVOICE

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE PTE LTD NO : AR202306-0011  
(10) GATEWAY DRIVE #15-08 CLAIM NO : QUOT202304-000030(01)  
WESTGATE TOWER DATE : 07/06/2023  
SINGAPORE 608531 POLICY NO : SP2003907937  
VEH REG : SNB6224E  
MAKE/MODEL : MERCEDES BENZ GLA200  
SUV PROGRESSIVE  
CHASIS NO : W1N2477872J306408  
ENGINE NO : 28291480657913  
REG. DATE : 2021

TEL : 6849 8118 FAX : 6849 8715

YOUR REF NO : 20233200700SL-GK-SNC4689E

CLAIM TYPE : THIRD PARTY

ACCIDENT DATE : 04/04/2023

TP VEHICLE NO : SNC4689E

## Final Repair Cost to Vehicle No : SNB6224E

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
NET PRICE			
1 Tailgate	1	2,455.00	2,455.00
2 Tailgate "GLA200" emblem	1	95.00	95.00
3 Tailgate centre logo	1	57.00	57.00
4 Rear bumper - upper	1	1,368.00	1,368.00
5 Rear bumper - lower	1	232.00	232.00
6 Rear bumper top chrome	1	345.00	345.00
7 Rear bumper reinforcement	1	524.00	524.00
8 Rear bumper centre inner frame	1	174.00	174.00
9 Rear bumper lower chrome	1	340.00	340.00
10 Rear bumper lower side bracket - LH	1	88.00	88.00
11 Front bumper	1	1,253.00	1,253.00
12 Front bumper reinforcement	1	505.00	505.00
13 Front bumper sponge	1	145.00	145.00
14 Front bumper inner support - top	1	86.00	86.00
15 Front bumper inner support - bottom	1	72.00	72.00
16 Front bumper lower chrome	1	305.00	305.00
17 Front number plate garnish	1	113.00	113.00
			8,157.00
		Less 10%	815.70
			7,341.30
SPECIAL NET			
18 Rear windscreen sealant	1	40.00	40.00
19 Tailgate "C&C" emblem	1	38.00	38.00
20 Front number plate	1	40.00	40.00
			118.00
LABOUR			
21 To transfer damaged tailgate interior mechanism to new tailgate	1	60.00	60.00



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

## TAX INVOICE

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE PTE LTD  
(TO) GATEWAY DRIVE#15-08  
WESTGATE TOWER  
SINGAPORE 608531

TEL : 6849 8118

FAX : 6849 8715

YOUR REF NO : 20233200700SL-GK-SNC4689E

CLAIM TYPE : THIRD PARTY

ACCIDENT DATE : 04/04/2023

TP VEHICLE NO : SNC4689E

NO : AR202306-0011  
CLAIM NO : QUOT202304-000030(01)  
DATE : 07/06/2023  
POLICY NO : SP2003907937  
VEH REG : SNB6224E  
MAKE/MODEL : MERCEDES BENZ GLA200  
SUV PROGRESSIVE  
CHASIS NO : W1N2477872J306408  
ENGINE NO : 28291480657913  
REG. DATE : 2021

### Final Repair Cost to Vehicle No : SNB6224E

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
22 To remove and refit rear windscreen glass	1	120.00	120.00
23 To remove and refit front & rear bumper sensor	1	120.00	120.00
24 To check and rectify wiring system	1	40.00	40.00
25 To panel beat and straighten rear floorboard panel, rear chassis frame, front support panel, front chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	800.00	800.00
26 To putty and spray on affected areas (front & rear)	1	880.00	880.00
27 To apply rust-proofing on replaced and repaired panels	1	30.00	30.00
			2,050.00
TOTAL:			<u>S\$9,509.30</u>
ADD GST @ 8%:			760.74
GRAND TOTAL:			<u><u>S\$10,270.04</u></u>

SINGAPORE DOLLARS TEN THOUSAND TWO HUNDRED AND SEVENTY AND CENTS FOUR ONLY

TONG LUCK AUTO PTE LTD

E. & O.E.

AUTHORISED SIGNATURE



> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 13 Apr 2023 / 14:33:29

Receipt Date/Time : 13 Apr 2023 / 14:33:29

### Tax Invoice/Receipt

Receipt No. : ITNET-00000-230413-002120

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-----	--	-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SNC4689E

As at 04 Apr 2023/17:45:00

Insurance Co: ALLIANZ INSURANCE SINGAPORE PTE. LTD.

1 Insurance Enquiry - SNC4689E

Enquiry Fee

20230413143132381866

24.77 1.98 26.75

**Sub-Total** 24.77 1.98 26.75

**Total Before Rounding** 24.77 1.98 26.75

**Rounding Difference** 0.00

**Total Amount Payable** 26.75

Paid By

518834XXXXXX2002 eNETS Credit Card 26.75

Total 26.75

Cash Change 0.00

Tendered Amount 26.75

Excess Refundable Amount 0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

## Enquire Vehicle's Insurance Particulars

### Thank You!

The insurance details of the vehicle you enquired can be found below. If you have entered a valid email address, a copy would have been sent to you.

**Vehicle No.**  
SNC4689E

**Incident Date/Time**  
04 Apr 2023 / 17:45:00

**Insurance Company Name**  
ALLIANZ INSURANCE SINGAPORE PTE.  
LTD.

[Save as PDF](#)

[OK →](#)

[Print](#)