

*Not known
Accident After Rain
@ 900h
4 days*

Date: 13/4/2023
Vehicle No: SJQ4744C
Model: MERCEDES E200 AVG AUTO
Chassis: WDD2130422A251133
Reg. Year: 2017

Third Party Insurer: AIG
Third Party Veh No: SMY4655Z
Date of Accident: 8/4/2023
Estimator: SIMON KOH
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR ASSY RH	1	\$ 2,497.00	\$ 2,497.00 X
2	REAR DOOR ASSY RH	1	REPAIR	\$ -
SUB TOTAL				\$ 2,497.00
LESS 10%				\$ 249.70
PARTS TOTAL				\$ 2,247.30

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1				\$ -
S/N TOTAL				\$ -

LABOUR CHARGES:

LABOUR TO REMOVE, REPLACE/REPAIR, REALIGN AND REFIX THE LISTED ACCIDENT AFFECTED DAMAGED PARTS \$ 600.00 300h

LABOUR TO REMOVE, TRANSFER AND REFIX FRONT RH DOOR AND REAR RH DOOR INNER MECHANISM AND DOOR TRIMS FROM DAMAGED DOORS TO NEW DOORS \$ 240.00 X

LABOUR TO PUTTY, RESPRAY AND POLISH FRONT RH DOOR ASSY, REAR RH DOOR ASSY AND OTHER ACCIDENT AFFECTED AREA \$ 600.00 ✓

TO TUFF KOTE AND UNDERSEAL MATERIALS \$ 120.00 X

LABOUR TOTAL \$ 1,560.00

TOTAL \$ 3,807.30

Simon

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before enter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- Through Motor Insurance Claims
- No valid insurance policy will be accepted

Supplementary item(s) must be presented and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

OH

Head Office
6 Woodlands Industrial Park Singapore 738043
Tel: 1-652-8472 1313 Fax: 1-652-8472 2112

Branch
8A Serangoon North Ave 5 Singapore 554809
Tel: 1-652-8424 0019 Fax: 1-652-8424 0023