

ASS. REC. BY: Taujit

REF: CS1/41523004077/Tops

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: _____

of _____

Insured: _____

Policy No. SP2003452035

Claims No. 202332005032

Sum Insured: _____ Excess: \$4500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: PD10184 Yr Regn: 2022, Dec.

Type: M.Gar / M.Cycle / ☒ Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Zhong Tong C.C. _____

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LDY ECS 23/N 0026054

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: ☒ M / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front 8 mm Rear 8 mm

R/Bal. 8 mm L/Bal. 8 mm

D.O.A. 30/1/2023 D.O.I. _____

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
17/5/23	Final fig \$12,490 confirmed by email (Red 6765, 35%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 19/5/23-typist

Repair Format: Merimen

Lump Sum / L.S. : \$12,490

Days Of Repair: 12

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

CONNECT 3

566 Woodlands Road Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R e c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

QT23/PD1018H/ODC

ALLIANZ INSURANCE COMPANY OF S'PORE PTE LTD
3 Temasek Avenue
#09-01 Centennial Tower
Singapore 039190

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PD1018H

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	LH side 2 nd exit door RH outer rubber moulding	1	860.00	cut ✓ 860.00
2.	LH side 2 nd exit door RH inner rubber moulding	1	730.00	cut ✓ 730.00
3.	LH 2 nd exit door LH & RH lower door panel	2	LH-Rx RH-bt ✓ 580.00 ✓	1,160.00
4.	LH 2 nd exit door upper lamp	1	235.00	? 235.00
5.	LH side glasses LH-wa ✓, RH X	1/2	1,600.00	3,200.00
6.	LH side glass frame	1	985.00	bt ✓ 985.00
7.	LH side lower panel (outer)	2	LH bt ✓ RH-Rx 1,250.00 ✓	2,500.00
8.	LH side handicap outer door switch	1	360.00	dis ✓ 360.00
9.	LH side emergency open door switch	1	400.00	dis ✓ 400.00
10.	LH side last door outer rubber moulding LH & RH	2	860.00	cut ✓ 1,720.00
11.	LH 2 nd door and last door upper linkage (steel)	2	380.00	? 760.00
12.	Reflector lamp	1	185.00	cut ✓ 185.00
13.	LH rear tyre	1	680.00	X 680.00
14.	Sealant	6/8	40.00	nee ✓ 320.00
15.	Labour to remove LH 2 nd & last exit door to assist repair	1	600.00	450 600.00


240 SW

16.	Labour to remove & refit LH side glasses to assist repair	1	600.00	450 600.00
17.	Transfer LH 2 doors fittings	1	500.00	X 500.00
18.	Wheel alignment & balancing	1	180.00	X 180.00
19.	Labour charges	1	1,800.00	1500 1,800.00
20.	Wiring for 2 exit doors & 2 door outer switch	1	280.00	180 280.00
21.	Spray painting	1	1,200.00	1000 1,200.00
SUB-TOTAL				SS19,255.00

- Price before gst

Thank you.

Yours faithfully



Winnie Chai
HP: 9850-9666

Tanah: 97495749
Rement, Not Authorise.
EX 84500
P/P Resurvey new parts
12 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: