



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR23004040/Rny3m4 Date: 23/05/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHF 185Z	Veh. Inspected	SMV 4072X
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/04/23/2028	Excess (\$)	0.00
	Assign From	ASHLENE LEE	Assign Date	19/04/2023
2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN GOLF 1.4 TSI CL	c.c	1395
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	WVWZZZAUZLW130550	Colour	WHITE
	Odometer	29278 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	PIRELLI	6 mm
	L/H Front Tyre	225/45 R17	PIRELLI	6 mm
	R/H Rear Tyre	225/45 R17	PIRELLI	6 mm
	L/H Rear Tyre	225/45 R17	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/04/2023	Inspection Date	20/04/2023
	Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	