


# Performance Motors

BMW Dealer



Lonpac Insurance Bhd  
300 Beach Road  
#17-04/07, The Concourse  
Singapore 199555

Attn: Motor Claims Dept.

LKK Ref: 23/23/VP05/027274  
Our ref: DS/SNB7300L

**Without Prejudice**

7 July 2023

## **ACCIDENT INVOLVING VEHICLES SNB7300L & SLK7138R ON 13/04/2023**

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows: -

Cost of Repair : \$2,668.84	Excess : \$ -
Loss of Use : \$ 300.00 (\$100 X 3 Days)	GIA/LTA Search : \$ 2.00
Loss of Rental : \$ -	Others : \$ -
	<b>Total : \$2,970.84</b>

A copy of each of the following supporting documents is enclosed:

1. Copy of Tax Invoice & Receipts
2. Copy of GIA/LTA search slip
3. Copy of GIA Report
4. Copy of Letter of Authorisation

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please email to [pml-pbsp@sime-darby.com.sg](mailto:pml-pbsp@sime-darby.com.sg).

Yours sincerely

Cresendo Lagman  
Customer Service Manager, Bodyshop

Bernard Wan  
Aftersales Manager, Bodyshop

Performance Motors Limited.  
Sime Darby Performance Centre, 303 Alexandra Road  
Sime Darby Business Centre, 315 Alexandra Road  
East Coast Centre, 280 Kampong Arang Road  
Ubi Service Centre, By-appointments only

Tel: 1800-2255-269  
Co Reg No. 197401559W

A Motors Company



A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)

## SERVICE TAX INVOICE

Repair Order No. : B1 1758879  
Date IN : 24/04/2023  
Motor Claim Advisor: Jack Ng Guo Ming

Page No. : 1 of 2  
Invoice Number : 2675791 / WSB  
Invoice Date : 27/06/2023  
Payment Terms : 30 Days From Invoice  
Invoice By : Mahamod Bin Mohd Sanif

## - CUSTOMER INFORMATION -

Sime Darby Services Private Limited  
305 Alexandra Road  
#02-01 Vantage Automotive Centre  
Singapore 159942

## - INVOICE TO - 158

Lonpac Insurance Bhd  
300 Beach Road  
#17-04/07 The Concourse  
Singapore 199555

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNB7300L	WBA12AK0207J73167	10/09/2021	218I GRAN COUPE	19405

## - - - - L A B O U R 1 - - - -

	NETT
Make good rear bumper and replace damaged attachment parts.	850.00
To respray rear bumper	986.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168.00
To check electrical wiring	168.00
Sundries.	40.00
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.	0.00
DATE OF ACCIDENT :13.04.2023. 3RD PARTY CAR :SLK7138R.	
YOUR REF NO :23/23/VP05/027274	
VEHICLE WAS SURVEYED BY RASUL FROM LKK ON 18.04.2023@1550HRS. AUTHORISED BY ENG HUEY NI FROM LONPAC VIA EMAIL ON 17.04.2023.	
PROPOSE LOSS OF USE = \$100X3 THE AMOUNT IS SUBJECTED TO	0.00
INSURANCE COMPANY CONFIRMATION.	
GIA SEARCH FEE = \$2.00.	0.00

Total Labour 1: **2,212.00**

## - - - - P A R T S - - - -

REAR BUMPER BOTTOM TRIM PANEL (M)

	Retail Qty	Price	NETT
	1	259.15	259.15
Total Parts :			<b>259.15</b>



A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)

**SERVICE TAX INVOICE**

Repair Order No. : B1 1758879	Page No. : 2 of 2
Date IN : 24/04/2023	Invoice Number : 2675791 / WSB
Motor Claim Advisor: Jack Ng Guo Ming	Invoice Date : 27/06/2023
	Payment Terms : 30 Days From Invoice
	Invoice By : Mahamod Bin Mohd Sanif

Labour Charges : 2,172.00	Total Labour & Parts Charges : S\$ 2,471.15
Parts Charges : 259.15	Less Insurance Excess : S\$ 0.00
Lubricant/Misc : 40.00	Invoice Total Amount Exclude GST : S\$ 2,471.15
	GST @ 8% : S\$ 197.69
	Invoice Total Amount Include GST : S\$ 2,668.84

Computer generated invoice. No signature is required.

Amount Payable Include GST : S\$ 2,668.84

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

17 APR 2023

Estimate No. : b1 65661  
Date Estimated : 17/04/2023  
Prepared By : Jack Ng Guo Ming

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -  
Sime Darby Services Private Limited  
305 Alexandra Road  
#02-01 Vantage Automotive Centre  
Singapore 159942

- ACCOUNT - 40000  
Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNB7300L	WBA12AK0207J73167	10/09/2021	218i Gran Coupe	19401

## DESCRIPTION

To replace rear bumper and all damage attachment

850 1,700.00

To respray rear bumper

986 1,088.00

To remove old PDC assembly, replace damaged parts and  
reconnect to new bumper including conduct check for  
proper function.

168 177.00

To check electrical wiring

168 177.00

Sundries.

7 150.00

Total Labour 1: 3,242.00

## DESCRIPTION

REAR BUMPER CARRIER ?

QTY	PRIC	VALUE
1	505.35	505.35

REAR BUMPER BOTTOM TRIM PANEL (M) *repair cut*

1	259.15	259.15
---	--------	--------

MOUNTING SMART OPENER (MSP) ?

1	48.45	48.45
---	-------	-------

REAR BUMPER PANEL PRIMED (MSP/PDC/repair)

1	1,360.35	1,360.35
---	----------	----------

REAR CENTRE GUIDE ?

1	163.55	163.55
---	--------	--------

Total Parts : 2,336.85

Claims OD (3rd Party) Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date & Time 18/04/23 @ 15:30 Excess S\$ \_\_\_\_\_Surveyor's Name RASHID Sign \_\_\_\_\_Surveyor's Tel 90010068 Authorised Yes / No \_\_\_\_\_

Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

SURVEY PARTS PHOTO BY SURVEYOR Yes / No \_\_\_\_\_ Part Yes / No \_\_\_\_\_

Surveyor's E-mail \_\_\_\_\_

No. of Working Days Recommended 3 days

Labour 1 : 3,242.00

Parts : 2,336.85

Labour 2 : 0.00

Excess : 0.00

Total GST @ 8% : 446.31

Grand Total : 6,025.16

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*


## INSURER ENQUIRY

**Find  
insurer**

Vehicle reg. no.

SLK7138R

Date of Accident

13/04/2023 

Reset

% **RESULT & RECEIPT**

## TP Insurer Enquiry

Insurance ..... **Lonpac Insurance Bhd**Period of Insurance ..... **24/01/2023 - 23/01/2024**Requested By ..... **Peh Ah Hoon (Performance Mo...**Requested Date ..... **14/04/2023 16:02****Payment details**Request Amount: **S\$1.85**GST Amount: **S\$0.15**Total Amount Due (GST Inclusive): **S\$2****General Insurance Association**

Records Management Centre

GST Registration No: **M400017735**

# Performance Motors Limited

A member of the Sime Darby Group



## LETTER OF AUTHORISATION

ACCIDENT INVOLVING SNB 7800L & SLK 7138R ON 12/24/2023.


I, SIME DARBY SERVICES PTE LTD owner of Vehicle Registration No. SNB 7800L,  
hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and  
settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all  
documents whatsoever in relation to this matter and to accept and receive any payment  
due to me in respect of my claim above.


I hereby declare that all acts and documents done by virtue of this Letter of Authorisation  
on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if  
the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement  
amount in respect of such claim shall constitute the full discharge of my claim in respect of  
such loss and damage.

Signed by:

  
Name : \_\_\_\_\_ (Date) \_\_\_\_\_  
NRIC No.: \_\_\_\_\_

In the presence of: **Jack Ng Guoming**  
Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

  
Name : \_\_\_\_\_ (Date) \_\_\_\_\_  
NRIC No.: \_\_\_\_\_