

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

HSBC LIFE (SINGAPORE) PTE LTD

10 MARINA BOULEVARD

#48-01 MARINA BAY FINANCIAL CENTRE

TOWER 2

SINGAPORE 018983 ATTN: OH VALE

PROFESSIONAL SERVICE FEE

Vehicle No. SMC 4501A

Insured Veh. SHC 3219G

Claim No. S3M04LQ1

Policy No. VFX/P2419138

Accident Date 15/04/2023

Inspection Date 20/04/2023

INV Date 09/05/2023

Reference CS3/HSB23004046/Tnp3e2

Code HSB

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 21.04.2023)	
Subtotal	100.00
GST (8%)	8.00
Grand Total	108.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'L'

'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM