



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)

Ref: CS/SPF23004049/y3

ACCIDENT CLAIMS SECTION

Date: 19/04/2023

(SPORE POLICE FORCE)

POLICE LOGISTICS BASE (PLB)

1 HEMMANT ROAD SINGAPORE 438675

Code: SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 482P	Veh. Inspected	SCG 8008D
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2023/024	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	19/04/2023

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/04/2023	Inspection Date
Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
