



Your Ref: 202332007297

Date: 05<sup>th</sup> May 2023

Our Ref: CS/AIS23004050/Wnp3e2

**M/s Allianz Insurance Singapore Pte Ltd**

79 Robinson Road #09-01

Singapore 068897

Dear Sir / Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE NO: YP 8202B  
ACCIDENT ON 13/04/2023**

**Instruction was received from Ms Janice Koh to inspect the vehicle Reg. No. YP 8202B at the premises of M/s: 160 Sin Ming Drive, #03-03, Sin Ming AutoCity, Singapore 575722, Repairer: Cheng Auto Bodyworks.**

The following information were recorded: -

<i>Registration Number</i>	: YP 8202B
<i>Make &amp; Model</i>	: Hino XZU710R-HKFMS3
<i>Chassis Number</i>	: JHHUCS3H00K023379
<i>Year of Registration</i>	: 2017
<i>Engine Capacity</i>	: 4009 cc
<i>Body colour</i>	: White

The following are our observation / comments:-

The vehicle sustained damages at the n/s body. (Details see photographs enclosed)

The repaired M/s Cheng Auto Bodyworks had agreed to undertake the repair of vehicle YP 8202B at Lump Sum \$6,000.00 before excess.

Enclosed please find damaged vehicle's photos and out invoices for your necessary action.

Yours faithfully



MUHAMMAD AKID BIN MOHAMED KAMAL  
Asst. Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.