nearside

offside

front

rear



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

DM23HO00782

Our ref:

CS/EQI23004051/Kwy3

Date: 24/05/2023

The Motor Claims Department

M/s EQ INSURANCE COMPANY LTD

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. <u>SMV 423T</u>

We thank you for your instruction on 19-04-23

Please be informed that we had conducted the inspection of the above mentioned vehicle on $\underline{20\text{-}04\text{-}23}$ at the premises of M/s $\underline{\text{OPTIMA WERKZ PTE LTD}}$ and have the following to report:-

Workshop Estimate Amount : \$\\$ 6,072.05

Revised Estimate Amount : \$\\$ 1,850.00 (Lump Sum)

"Check" Items Amount

Market Value

LTA Reimbursement Value

Nett Value

Description of Damage:
The vehicle sustained damages at the

O/S Front portion.

Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Please note that the preliminary advise amount (Revised & check items) stated are subject to consistency check, part prices and labour cost.

Yours faithfully,

Kenneth Kong Automotive Assessor