

Date: 18/4/2023
Vehicle No: SMV423T
Model: NISSAN SERENA 1.2L HIGHWAY STAR
Chassis: JN1EBAC27Z0000592
Reg.Year: 2020

Third Party Insurer: EQ INSURANCE
Third Party Veh No: GBF7299D
Date of Accident: 10/4/2023
Estimator: SIMON KOH
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR ASSY RH	1	\$ 1,680.00	\$ 1,680.00
2	FRONT DOOR LOWER PROTECTOR RH	1	\$ 735.00	\$ 735.00
3	FRONT FENDER PROTECTOR RH	1	\$ 252.00	\$ 252.00
4	E-POWER EMBLEM	1	\$ 157.50	\$ 157.50
5	SIDE MIRROR ASSY RH	1	\$ 2,100.00	\$ 2,100.00
SUB TOTAL				\$ 4,924.50
LESS 10%				-\$ 492.45
PARTS TOTAL				\$ 4,432.05

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1				\$ -
2				\$ -
S/N TOTAL				\$ -

LABOUR CHARGES:

LABOUR TO REMOVE, REPLACE/REPAIR, REALIGN AND REFIX THE LISTED ACCIDENT AFFECTED DAMAGED PARTS \$ 600.00

LABOUR TO REMOVE, TRANSFER AND REFIX FRONT RH DOOR INNER MECHANISM FROM DAMAGED DOOR ASSY TO NEW DOOR ASSY \$ 120.00

LABOUR TO PUTTY, RESPRAY AND POLISH FRONT RH DOOR, FRONT RH FENDER, FRONT RH DOOR PROTECTOR, FRONT RH FENDER PROTECTOR AND OTHER ACCIDENT AFFECTED AREA \$ 800.00

TO TUFF KOTE AND UNDERSEAL MATERIALS \$ 120.00
LABOUR TOTAL \$ 1,640.00

Simon TOTAL \$ 6,072.05

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

