

JAS AUTO SERVICES

UEN: 53255447k

60 JALAN LAM HUAT
#05-06/07 CARROS CENTRE
SINGAPORE 737869

Our Ref : 0
Accident date : 10/4/2023
Your Ref : SLH3227J

Invoice No:

Date :

4/26/2023

Motor Claim Department
Auto & General Insurance(Singapore) Pte Ltd
190 Clemenceau Avenue
#03-01 Singapore Shopping Centre
S(239924)

SUPPLEMENTARY COST OF REPAIRS TO

Vehicle No. : SJQ1775H
Model : Suzuki Swift

1 pc Rear right fender innershield Cut \$ 107.00 ✓

Less 15%

\$	107.00
\$	(16.05)
\$	90.95 ✓

1415.25 + 90.95
= 1506.2

Labour: 450

1956.2

20% = 391.24

= 1564.96

= \$1560.00

JAS AUTO SERVICES