



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS3/LIP23004078/Wqy3 Date: 20/04/2023 Code: LIP	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
	Insured Veh.	SMT 2752R	Veh. Inspected	FBR 1066K
	Policy No.		Coverage (\$)	0.00
	Claim No.	IVS23/0756	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	19/04/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
	Accident Date	06/04/2023	Inspection Date	20/04/2023
	Survey held at	TWO-WHEELED AFFAIR 39 WOODLANDS CLOSE, #03-04, MEGA@WOODLANDS, SINGAPORE 737856		
<b>5a. Remarks</b>				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			