



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23004079/Uqy3e2	
			Date: 15/05/2023	
			Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGP 4013U	Veh. Inspected	SJF 9145G
	Policy No.		Coverage (\$)	0.00
	Claim No.	IVS23/0762	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	20/04/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VIOS (A)	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	MR053HY9305067532	Colour	WHITE
	Odometer	242460 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/45Z R16	ROTALLA	7 mm
	L/H Front Tyre	205/45Z R16	ROTALLA	7 mm
	R/H Rear Tyre	205/45Z R16	ROTALLA	7 mm
	L/H Rear Tyre	205/45Z R16	ROTALLA	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	18/04/2023	Inspection Date	20/04/2023
	Survey held at	ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130		
5a. Remarks				
	A)REGISTRATION DATE: 16 JUN 2008 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	