



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD
10 EUNOS ROAD 8
SINGAPORE POST CENTRE #09-04A
SINGAPORE 408600

Ref: CS/ICS23004080/Wwy3

Date: 20/04/2023

Code: ICS

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKQ 3374G	Veh. Inspected	GBC 7984A
Policy No.		Coverage (\$)	0.00
Claim No.	DMPC2300243H/ST	Excess (\$)	0.00
Assign From	SHARON TAN	Assign Date	20/04/2023

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	04/04/2023	Inspection Date	20/04/2023
Survey held at	AUTO INSURE PTE LTD 6 MARSILING LANE S739145		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.