

Shiau Chan (LKKAUTO)

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Thursday, 27 April 2023 9:34 AM  
**To:** HanZC  
**Cc:** SUR; Gary Seah  
**Subject:** RE: Allianz OD SMX7101R  
**Attachments:** SMX7101R revise Estimate.pdf

Dear Han,

Please proceed the check items as marking by our surveyor as attached and take note that the repair cost at \$8,884.61 on part by part basis. (excess \$700/-)

Best Regards,

**Shiau Chan (Ms)** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** HanZC <hanzc@smemotor.com.sg>  
**Sent:** Wednesday, April 26, 2023 2:20 PM  
**To:** Huey Yon (LKKAUTO) <hueyyon@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>; Gary Seah <gary.seah@smemotor.com.sg>  
**Subject:** Allianz OD SMX7101R

Dear Huey Yon,

Your surveyor has conducted the physical re-inspection on the check items that are damaged after dismantle, attached the Marked Estimate.

Kindly assist to revert to the insurance and update us once approval is given.

Thanks.

Best Regards

Han ZC  
SME MOTOR PTE LTD  
1 Kaki Bukit Ave 6  
Blk D, #02-15/16/17/18  
AutoBay @ Kaki Bukit  
Singapore 417883  
Tel: 6747 6106 (6 lines)  
Fax: 6744 2368