

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/04/2023
User ID : munsan

TP
40m

Section A - Accident Details

Registration Number	SHB1051R
Case Reference Number	TAX/04/23/2030
Registration Date	17/12/19
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	SHAHLAN BIN SHAMSURI
Type of Accident	Side Swipe
Accident Date and Time	15/4/23 9:38 PM
Accident Reported Date and Time	17/4/23 11:06 AM
Insurance Surveyor Required?	No
Surveyed by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24118181
Special Instruction to ARC, if any	TP/ RIGHT REAR PORTION/ DROVE IN
Prepared Date and Time	17/4/23 1:10 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$0.00
Total Spray Cost	\$1,952.00	\$0.00
Total Spare Part Cost	\$6,263.38	\$0.00
Total Other Cost	\$860.00	\$0.00
TOTAL COST	\$10,089.38	\$0.00
Temp Sum Total	\$10,100.00	\$0.00
Number of Repair Days	7.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date		
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 6365592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/04/2023

User ID : muanan

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
O REPAIR REAR PORTION RH	\$1,014.00 <i>2001</i>	
total Labour	\$1,014.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O RESPRAY RIM	\$220.00 <i>na X</i>	
O RESPRAY REAR BUMPER	\$378.00 <i>na X</i>	
O RESPRAY REAR FENDER RH	\$378.00 <i>na X</i>	
O RESPRAY RH REAR DOOR	\$378.00 <i>na X</i>	
O RESPRAY ROCKER PANEL MOULDING	\$220.00 <i>na X</i>	
O RESPRAY FRONT DOOR RH	\$378.00 <i>na X</i>	
total Spray Painting & Panel Beating	\$1,952.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O WASH AND VACUUM	\$60.00 <i>na X</i>	
O CHECK WIRING AND SYSTEM FUNCTION	\$120.00 <i>201</i>	
O APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00 <i>301</i>	
O DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00 <i>na X</i>	
O REMOVE AND REFIT TYRE	\$120.00 <i>na X</i>	
O TRANSFER DOOR MECHANISM	\$120.00 <i>601</i>	
O TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00 <i>na X</i>	
O REPLACE SUNDRY PARTS	\$100.00 <i>na X</i>	
total Other Costs	\$860.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52023-47030	REAR BUMPER REINFORCEMENT	1.00	\$360.10	25.00	\$270.08	Replace <i>na</i>	X
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$525.40	25.00	\$394.05	Replace <i>na</i>	X
		52462-47130	PAD, RR BUMPER, RH & LH, 3	2.00	\$12.00	25.00	\$18.00	Replace <i>na</i>	X
		52462-47030	PAD, RR BUMPER, RH & LH, 2	2.00	\$4.30	25.00	\$6.45	Replace <i>na</i>	X
		52462-47020	PAD, RR BUMPER, RH & LH, 1	2.00	\$4.30	25.00	\$6.45	Replace <i>na</i>	X
		52575-47060	RETAINER, RR BUMPER, RH	1.00	\$143.60	25.00	\$107.70	Replace <i>na</i>	X
		52591-47080	SEAL, RR BUMPER, RH	1.00	\$128.00	25.00	\$96.00	Replace <i>na</i>	X
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace <i>na</i>	X
		52453-47900	GUARD, RR BUMPER, LOWER	1.00	\$405.00	25.00	\$303.75	Replace <i>na</i>	X
		52169-47070	COVER, GUARD RR BUMPER LOWER	1.00	\$23.90	25.00	\$17.92	Replace <i>na</i>	X
		81910-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, RH	1.00	\$42.20	25.00	\$31.65	Replace <i>na</i>	X
		58398-47050	COVER, REAR FLOOR UNDER, RH	1.00	\$189.20	25.00	\$141.90	Replace <i>na</i>	X
		67003-47211	PANEL SUB-ASSY, REAR DOOR, RH	1.00	\$1,401.70	25.00	\$1,051.28	Replace <i>na</i>	✓
		68630-47050	CHECK ASSY, REAR DOOR	1.00	\$199.40	25.00	\$149.55	Replace <i>na</i>	X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
81 Woodlands Industrial Park E4, Singapore 757025
FAX Number : 68662652
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/04/2023

User ID : murson

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67971-47057	WEATHERSTRIP, REAR DOOR RH	1.00	\$144.90	25.00	\$108.68	Replace	PN X
		68752-20122	HINGE ASSY, REAR DOOR, UPPER RH	1.00	\$107.00	25.00	\$80.25	Replace	R X
		68772-52021	HINGE ASSY, REAR DOOR, LOWER RH	1.00	\$83.90	25.00	\$62.93	Replace	R X
		68720-47150	DOOR REAR MOTOR ASSY, POWER WINDOW REGULATOR, RH	1.00	\$886.60	10.00	\$886.94	Replace	? ?
		68803-47020	DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	1.00	\$223.50	25.00	\$167.63	Replace	? ?
		75852-47910	MOULDING ASSY, BODY ROCKER PANEL, RH	1.00	\$486.10	25.00	\$486.63	Replace	PN X
		67001-47153	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,407.80	25.00	\$1,055.85	Replace	R X
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	NN X
		61601-47150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$843.10	25.00	\$707.33	Replace	R X
		4261147450	WHEEL DISC	1.00	\$2,036.30	25.00	\$1,527.23	Replace	PN X
		42452-76020	HUB & BEARING ASSY WITH SPEED SENSOR, REAR AXLE, RH & LH	1.00	\$644.10	10.00	\$579.69	Replace	NN X
Total					\$10,798.90		\$8,408.91		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: