

Huey Yon (LKKAUTO)

From: Simon Ho (LKKAUTO)
Sent: Thursday, 11 May 2023 10:06 AM
To: Huey Yon (LKKAUTO)
Subject: Re: ICS-TP / SLP 7102S -SURVEY BY Kenneth (CS/ICS23004119/Kny3)

Dear Huey Yon,

Audit check done for SLP7102S without problem.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Huey Yon (LKKAUTO) <hueyyon@lkkauto.com>
Sent: Thursday, 11 May 2023 9:15 am
To: Simon Ho (LKKAUTO) <SimonHo@lkkauto.com>
Subject: RE: ICS-TP / SLP 7102S -SURVEY BY Kenneth (CS/ICS23004119/Kny3)

Dear Simon,

For your re-audit -wheel alignment report uploaded.

Best Regards,

Huey Yon | Case Handler

LKK Auto Consultants

phone: 6256-3561 | email: hueyyon@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Simon Ho (LKKAUTO) <SimonHo@lkkauto.com>
Sent: Wednesday, May 10, 2023 1:19 PM
To: Huey Yon (LKKAUTO) <hueyyon@lkkauto.com>
Subject: Re: ICS-TP / SLP 7102S -SURVEY BY Kenneth (CS/ICS23004119/Kny3)

Dear Huey Yon,

Audit check done for SLP7102S, found no wheel alignment report upload.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Huey Yon (LKKAuto) <hueyyon@lkkauto.com>

Sent: Wednesday, 10 May 2023 1:07 pm

To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>

Subject: RE: ICS-TP / SLP 7102S -SURVEY BY Kenneth (CS/ICS23004119/Kny3)

Dear Simon,

For your re-audit.

Best Regards,

Huey Yon | Case Handler

LKK Auto Consultants

phone: 6256-3561 | email: hueyyon@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>

Sent: Monday, April 24, 2023 2:25 PM

To: Huey Yon (LKKAuto) <hueyyon@lkkauto.com>

Subject: Re: ICS-TP / SLP 7102S -SURVEY BY Kenneth (CS/ICS23004119/Kny3)

Dear Huey Yon,

Audit check done for SLP7102S, found some parts prices need verification.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Huey Yon (LKKAuto) <hueyyon@lkkauto.com>

Sent: Monday, 24 April 2023 1:55 pm

To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>

Subject: ICS-TP / SLP 7102S -SURVEY BY Kenneth (CS/ICS23004119/Kny3)

