

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI23004134/Kvy3q2	
		TINSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date	: 03/05/2023	
			Code	e: AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJH 2732Y	Veh. Inspected	SHD 1000C	
	Policy No.	P10552806R01	Coverage (\$)	0.00	
	Claim No.	C10021349/KY	Excess (\$)	0.00	
	Assign From	DON BONG	Assign Date	21/04/2023	
2. Vehicle Particulars & Condition					
	Make & Model	RENAULT LATITUDE (A)	c.c	1995	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	VF1ABL15AUC283374	Colour	METALLIC WHITE/RED	
	Odometer	420213 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	215/60 R16	SAILUN	6 mm	
	L/H Front Tyre	215/60 R16	SAILUN	6 mm	
	R/H Rear Tyre	215/60 R16	FALKEN	5 mm	
	L/H Rear Tyre	215/60 R16	FALKEN	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	28/03/2023	Inspection Date	24/04/2023	
	Survey held at	TRANS-CAB AUTO SERVICES	PTE LTD		
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a.	. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: