

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

20/4/2023

LONPAC INSURANCE BHD
300 BEACH ROAD
17-04/07 THE CONCOURSE
SINGAPORE 199555

Vehicle No: SMZ2507B
Vehicle Model: SKODA OCTAVIA
Est No: CD2862
Claims ref:
Accident Date: 13/04/23
In Charge: JUNIOR
Remarks:

No	Description	Qty	U. Price	Amounts S\$
LIST ITEMS:				
1	FRONT BUMPER	1 PC	\$ 1,875.00	\$ 1,875.00
2	FRONT BUMPER RETAINER RH / LH	2 PC	\$ 87.50	\$ 175.00
3	FRONT BUMPER CLIPS	10 PC	\$ 4.50	\$ 45.00
4	RADIATOR GRILLE BASE W GRILLE	1 PC	\$ 920.00	\$ 920.00
5	FRONT BONNET	1 PC	\$ 2,875.00	\$ 2,875.00
6	FRONT EMBLEM "SKODA" LOGO	1 PC	\$ 167.25	\$ 167.25
7	RADIATOR TOP COVER CLIPS	10 PC	\$ 4.50	\$ 45.00
8	FRONT BONNET LOCK ASSY	1 PC	\$ 262.50	\$ 262.50
9	RADIATOR GRILLE OUTER CHROME	1 PC	\$ 985.20	\$ 985.20
10	H/LAMP LH & RH C/W GRILLE SIDELAMP	2 PC	\$ 2,875.50	\$ 5,751.00
11	FRONT BUMPER SPONGE	1 PC	\$ 192.50	\$ 192.50
12	FRONT BUMPER REINFORCEMENT	1 PC	\$ 937.50	\$ 937.50
13	FRONT BUMPER SPONGE - CHECK	1 PC		\$ -
LIST TOTAL S\$				\$ 14,230.95
15% COST PLUS S\$				\$ 2,134.64
				<u>\$ 16,365.59</u>

LABOUR CHARGE:

1	TO CUT, WELD, JACK, STRAIGHTEN, REPLACE DAMAGED PARTS & REALIGN AFFECTED AREAS	\$ 600.00
2	TO PUTTY SPRAY PAINT ON BONNET, FRONT BUMPER & AFFECTED AREAS	\$ 600.00
3	TO RUST PROOF ON AFFECTED AREAS	\$ 100.00
4	TO TRANSFER FRONT BUMPER PARKING SENSOR	\$ 80.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	\$ 80.00

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel : (65) 6272 3892
Fax : (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

20/4/2023


LONPAC INSURANCE BHD
300 BEACH ROAD
17-04/07 THE CONCOURSE
SINGAPORE 199555

Vehicle No: SMZ2507B
Vehicle Model: SKODA OCTAVIA
Est No: CD2862
Claims ref:
Accident Date: 13/04/23
In Charge: JUNIOR
Remarks:

No	Description	Qty	U. Price	Amounts S\$
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS			\$ 280.00
7	TO REMOVE & REFIT BONNET MECHANISM & OTHER ATTACHMENT PARTS			\$ 80.00
TOTAL LABOUR COST S\$				<u>\$ 1,820.00</u>

AMOUNT S\$ \$ 18,185.59
GST @ 8% \$ 1,454.85
AMOUNT DUE S\$ \$ 19,640.44

Customer's Signature


MOVA AUTOMOTIVE PTE LTD