

SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO.: /20230413/0058	3	LOCATION OF FIRE: Open Space Car Park	
FIRE REPORTED ON: 13 April 2	023		
TIME OF CALL: 01:46:18 hrs		Along Desker Road, In front of Unit 91 Singapore 209613	
STATION COVERAGE: Central Fire Station	n		
2. INCIDENT INFORMATION			
FIRE INVOLVED: The dashboard of a BMW car (SNG1790T).			
METHOD OF EXTINGUISHMENT: By a member of public using two dry powder fire extinguishers before the arrival of SCDF crew.			
PROBABLE CAUSE OF FIRE: Accidental (Electrical origin at the dashboard)			
DAMAGE OBSERVED*: As a result of the fire, the dashboard of the car was damaged. Other parts of the car sustained heat, smoke and water damage.			
3. FATALITY/INJURY INFORMATION			
NAME	NRIC/FIN		DEAD/INJURIES SUSTAINED
NIL	NIL		NIL
REPORT ISSUED BY: NICK LI KEJING for COMMISSIONER SINGAPORE CIVIL DEFENCE E	ORCE		

This is a computer generated report. No signature is required.

^{*}This is based on observations made by the fire investigator incidental to his/her investigation to determine the cause and origin of the fire, and is not to be taken as an exhaustive list of damage caused by the fire.