



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS3/LIP22012502/Knp3m4-1 Date: 26/04/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMD 2359C	Veh. Inspected	SLF 1911R
	Policy No.	SD22V00091/VPZ/R02	Coverage (\$)	0.00
	Claim No.	BVS22/1451	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	21/04/2023
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES GLB200 (A)	c.c	1332
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	W1N2476872W050556	Colour	METALLIC GREY
	Odometer	24867 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/50 R19	PIRELLI	6 mm
	L/H Front Tyre	235/50 R19	PIRELLI	6 mm
	R/H Rear Tyre	235/50 R19	PIRELLI	7 mm
	L/H Rear Tyre	235/50 R19	PIRELLI	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/12/2022	Inspection Date	19/12/2022
	Survey held at	A T PERFORMANCE 160 SIN MING DRIVE #07-18/19 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)REGISTRATION DATE: 25 MAR 2021 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	