

TP / Liberty Insurance



86667775

CHENG AUTO
Bodyworks

CHENG AUTO BODYWORKS

Co. Reg. No. 53315238X | GST Reg. No. M90372111L

5 Soon Lee Street, #01-60 Pioneer Point, Singapore 627607

☎ 6631 0707 ✉ cab@chengauto.com 📱 Cheng Auto Bodyworks Singapore

Date: 25 April 2023

REPAIR DETAILS		
REFERENCE		
Vehicle Reg. No.	GBC8308X	45 TP
Make & Model	TOYOTA / TOYOTA DYNA 150 MANUAL	
Chassis No.	JTFAT35YX0K202674	
Engine No.	1KD2344804	
Manufacture Year	2013	
TP Vehicle Reg. No.	YQ7077Y	
DOA & Location	13-04-2023	
		ALONG KIAN TECK ROAD

ESTIMATES OF PARTS

No.	Description	Qty	Price
1	WINDSCREEN X nn	1	\$ 1,674.02
2	WINDSCREEN MOULDING X nn	1	\$ 395.26
3	CENTRE PANEL X nn	1	\$ 1,277.90
4	GRILLE ASSY X nn	1	\$ 636.86
5	HEADLAMP LH sou	1	\$ 1,260.67 856 ✓
6	SIDE CORNER PANEL LH 4	1	\$ 349.46 276 ✓
7	SIDE CORNER MOULDING BLACK LH X nn	1	\$ 82.50
8	PARKING MIRROR LH GARNISH COVER mis	1	\$ 92.40 ✓
9	DOOR LH repair X	1	\$ 1,811.60
10	DOOR LH HINGE UPPER X nn	1	\$ 142.10
11	DOOR LH HINGE LOWER X nn	1	\$ 142.10
12	ROUND PARKING MIRROR mis	1	\$ 98.60 ✓
13	PARKING MIRROR STAND LH 4	1	\$ 104.50 ✓
14	EMBLEM DYNA X nn	1	\$ 68.80
15	BUMPER BRACKET LH X nn	1	\$ 253.80
16	STEP GARNISH LH X nn	1	\$ 375.30

17. Windscreen Lower panel 40.00 X nn	Sub-Total (\$\$)	\$ 8,765.87
18. Front Bumper 4	SAAA List Item Discount 25% (\$\$)	\$ 2,191.47
	Total Parts (\$\$)	\$ 6,574.40

LABOUR

2108.50
-25%
1581.37

No.	Description	Price
1	LABOUR	\$ 1,600.00 sou
2	SPRAYPAINTING	\$ 1,400.00 bou
3	REMOVE AND REINSTALL ROOF AC ASSY TO CHECK	\$ 400.00 X
4	REMOVE AND REINSTALL INNER TRIM, GARNISH, ROOF LINING AND/OR UPHOLSTERY TO FACILITATE REPAIRS	\$ 300.00 X

5	REMOVE AND REPLACE FRONT WINDSCREEN	\$	150.00
6	ALIGNMENT	\$	150.00

Total Labour (\$\$) \$ 4,000.00 1100

MISCELLANEOUS ITEMS

No.	Description	Price	
1	AC GAS	\$ 200.00	nn
2	COMPANY STICKER LOGO DOOR	\$ 400.00	150 nec
3	COMPANY STICKER	\$ 30.00	nec
Total Miscellaneous Items (\$\$)		\$ 630.00	180

2861.37

L/S - 2289.10
= 2300

Total Parts (\$\$)	\$	6,574.40
Total Labour (\$\$)	\$	4,000.00
Total Miscellaneous (\$\$)	\$	630.00
Total (\$\$)	\$	11,204.40
GST 8% (\$\$)	\$	896.35
Grand Total (\$\$)	\$	12,100.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resul
Hy 90010068
4 days
4/5
25/04/23 P1410
Resurvey after repair