



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CS3/MSG22008744/Dqy3-1

MSIG INSURANCE (S) PTE LTD
4 SHENTON WAY #21-01
SGX CENTRE 2 SINGAPORE 068807

Ref: ~~CS3/MSG22008744/Cay3~~
Date: ~~06/09/2022~~ 25/04/2023
Code: MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBE 4371C	Veh. Inspected	SLD 3235G
Policy No.	1001211166	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	RICHARD ANG WEI GUANG	Assign Date	06/09/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	04/09/2022	Inspection Date	06/09/2022
Survey held at	D'S GRAFFITI CONCEPTS PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.