

Estimate

MOVA AUTOMOTIVE PTE LTD 1008 BUKIT MERAH , LANE 3 #01-04 SINGAPORE 159722, Singapore, Singapore, Singapore - 159722. VAT: 198904033G Contact: +65 62723892 Email: NITHA@MOVA.COM.SG	Proforma Invoice No:	Date: Apr 25 2023
	Ticket No: MAP-J000023	Vehicle No: SJN6702B
	Policy No: 000	Claim No: 0
	Customer: Lim Eng Tiong Vehicle: HONDA FREED 1.5 G 2009 Kilometer: 244926 Color: WHITE Fuel: PETROL PH: +65 96550338 Email:	
Company Name: INDIA INTERNATIONAL INSURANCE Address: 64 Cecil Street,#04-02 IOB Building City: Singapore Region: Central Singapore Postal Code: 049711 Co.Reg.No: 198703792K		

#	Part Name	Description	GST (%)	Quantity	Unit Price	Payable Amount	Discount	Taxable	Parts Total
1	FRONT FENDER LH	Part	8	1.00	484.80	387.84	96.96	387.84	418.87
2	FRONT FENDER COWLING LH	Part	8	1.00	90.50	72.40	18.10	72.40	78.19
3	FRONT FENDER COWLING CLIPS	Part	8	10.00	5.90	4.72	11.80	47.20	50.98
4	FRONT DOOR LH	Part	8	1.00	911.40	729.12	182.28	729.12	787.45
5	FRONT DOOR HINGE TOP LH	Part	8	1.00	34.10	27.28	6.82	27.28	29.46
6	FRONT DOOR HINGE BOTTOM LH	Part	8	1.00	52.10	41.68	10.42	41.68	45.01
7	FRONT DOOR OUTER MOULDING LH	Part	8	1.00	75.50	60.40	15.10	60.40	65.23
8	FRONT DOOR STICKER LH	Part	8	1.00	60.10	48.08	12.02	48.08	51.93
9	FRONT DOOR LOCK LH	Part	8	1.00	310.40	248.32	62.08	248.32	268.19
10	FRONT DOOR WEATHERSTRIP LH	Part	8	1.00	84.70	67.76	16.94	67.76	73.18
11	FRONT DOOR GLASS REGULATOR C/W MOTOR LH	Part	8	1.00	381.70	305.36	76.34	305.36	329.79
12	FRONT DOOR TRIM BOARD LH	Part	8	1.00	911.70	729.36	182.34	729.36	787.71
13	CENTER PILLAR LH	Part	8	1.00	1,015.80	812.64	203.16	812.64	877.65
14	ROCKER PANEL LH	Part	8	1.00	480.70	384.56	96.14	384.56	415.32
15	REAR SLIDING DOOR LH	Part	8	1.00	2,181.70	1,745.36	436.34	1,745.36	1,884.99
16	REAR SLIDING DOOR STICKER LH	Part	8	1.00	35.30	28.24	7.06	28.24	30.50
17	REAR SLIDING DOOR STICKER - MANUEL DOOR PULL & SLIDE TO OPEN	Part	8	1.00	60.00	60.00	0.00	60.00	64.80
18	REAR SLIDING DOOR LOCK	Part	8	1.00	364.10	291.28	72.82	291.28	314.58
19	REAR SLIDING DOOR WEATHERSTRIP	Part	8	1.00	107.40	85.92	21.48	85.92	92.79
20	REAR SLIDING DOOR ROLLER BOTTOM LH	Part	8	1.00	174.30	139.44	34.86	139.44	150.60
21	REAR SLIDING DOOR GLASS REGULATOR MOTOR LH	Part	8	1.00	359.40	287.52	71.88	287.52	310.52
22	REAR SLIDING DOOR INNER TRIM LH	Part	8	1.00	1,214.80	971.84	242.96	971.84	1,049.59
							Taxable Value	7,571.60	
							GST Total	605.73	
							Discount Total	1,877.90	
							Grand Total	8,177.33	

#	Service	Description	GST (%)	Quantity	Unit Price	Payable Amount	Discount	Taxable	Labour Total
23	TO CUT / WELD CENTER PILLAR LH, ROCKER PANEL LH, KNOCK & STRAIGHTEN REAR FENDER LH, REMOVE & REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION	Labour	8	-	1,000.00	1,000.00	0.00	1,000.00	1,080.00
24	SPRAY PAINT FRONT FENDER LH, FRONT DOOR PILLAR LH, FRONT DOOR LH , CENTER PILLAR LH, ROCKER PANEL LH, REAR SLIDING DOOR LH, REAR FENDER LH	Labour	8	-	1,400.00	1,400.00	0.00	1,400.00	1,512.00
25	REMOVE & REPLACE FRONT SEAT ASSSY, CENTER PILLAR INNER TRIM LH, FRONT SEAT	Labour	8	-	200.00	200.00	0.00	200.00	216.00

#	Service	Description	GST (%)	Quantity	Unit Price	Payable Amount	Discount	Taxable	Labour Total
26	BELT LH, FLOOR CARPET, UPHOSTERY REMOVE & REPLACE FRONT & REAR DOOR TRIM BOARD,MECHANISM & LOCKING SYSTEM	Labour	8	-	120.00	120.00	0.00	120.00	129.60
27	RUST PROOF AFFECTED AREAS & REAR FENDER (REPAIR)	Labour	8	-	120.00	120.00	0.00	120.00	129.60
							Taxable Value 2,840.00 GST Total 227.20 Discount Total 0.00 Grand Total 3,067.20		

						Parts Total 7,571.60 Labour Total 2,840.00 GST Total 832.93 Grand Total 11,244.53 Balance 11,244.53
--	--	--	--	--	--	--

I certify that the work has been done to my satisfaction and that I have taken delivery of the vehicle in good condition, with all items / valuables and parts intact.

Customer / Authorized Signatory

Service Advisor Signature

Cashier / Authorized Signature