



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-008864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System,

Hilton Car Rental Centre
Hilton Auto Trading

Dealing in New/Used Cars, Hire Purchase & Insurance.



INSURER:

Allianz Insurance Singapore Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2003708419	Date of Loss:	16/04/2023
Vehicle Reg. No.:	SFU8889T	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KEE KOH LEONG		
Make/Model:	TOYOTA HARRIER, 2.0 M GRADE (A)	Vehicle Reg. Date:	07/01/2019
Vehicle Colour:	WHITE	Chassis No:	JTEZB3GH30J004158
Engine No:	8ARZ148496		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		

Present Location: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)

COST OF CLAIMS

	Amount
Parts	4,845.50
Miscellaneous Items	0.00
Labour	2,330.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	7,175.50
+ GST 8.00% (S\$)	574.04
Nett Amount (S\$)	7,749.54

This claim is handled by: BILLY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 26 Apr 2023)**Parts:** M1-SUV TOYOTA HARRIER 2.0 M GRADE (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Mova Automotive Pte Ltd/SFU8889T/26/04/2023 09:43**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT FENDER RH	0.00	0.00	*380.00 F	BUC
2	1		*FRONT FENDER COWLING RH	0.00	0.00	*185.00 F	DIS
3	10		*FRONT FENDER COWLING CLIPS	0.00	0.00	*25.00 F	NEC
4	1		*FRONT SPORT RIM RH	0.00	0.00	*1,680.00 F	CUT
5	1		*FRONT WHEEL HUB RH BEARING	0.00	0.00	*250.00 F	X NN
6	1		*FRONT KNUCKLE ARM RH	0.00	0.00	*240.00 F	X NN
7	1		*FRONT LOWER ARM RH	0.00	0.00	*220.00 F	X NN
8	1		*FRONT DOOR RH	0.00	0.00	*720.00 F	BUC
9	1		*FRONT DOOR STICKER RH	0.00	0.00	*90.00 F	NEC
10	1		*FRONT DOOR CHROME MOULDING RH	0.00	0.00	*125.00 F	CUT
11	1		*FRONT DOOR PILLAR RH (REPAIR)	0.00	0.00	-	
12	1		*REAR DOOR RH (REPAIR)	0.00	0.00	-	
13	1		*REAR DOOR CHROME MOULDING RH	0.00	0.00	*90.00 F	CUT
14	1		*ROCKER PANEL GARNISH RH	0.00	0.00	*400.00 F	X NN

F=Franchise part.

Sub Total (\$\$)

4,405.00

+ Margin on L,N Items 10.00% (\$\$)

440.50

Total Parts (\$\$)

4,845.50

Mova Automotive Pte Ltd/SFU8889T/26/04/2023 09:43. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK & STRAIGHTEN FRONT DOOR PILLAR RH, REMOVE & REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION	New	600.00 <i>400</i>
2	SPRAY PAINT FRONT FENDER RH, FRONT DOOR PILLAR RH, FRONT DOOR RH, REAR DOOR RH. (PEARL COLOUR)	New	1,400.00 <i>800</i>
3	REMOVE & REPLACE FRONT DOOR INNER TRIM, MECHANISM & CHECK LOCKING SYSTEM	New	60.00 ✓
4	REMOVE & REPLACE FRONT DOOR PILLAR GARNISH RH, COVERING TRIM	New	60.00 <i>3</i> ✓
5	REMOVE & REPLACE FRONT UNDER CARRIAGE SUSPENSION RH	New	150.00 ✓
6	COMPUTER WHEEL ALIGNMENT	New	60.00 ✓
Gross Labour Cost (S\$)			2,330.00

Mova Automotive Pte Ltd/SFU8889T/26/04/2023 09:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- Not authorise.
- Excess = \$? (TBA)
- Resurvey before paint for P/P repair.
- Survey by Simon Ho (62563561)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: