

(08/11/13) wef

ASS. REC. BY:

Simon Ho

REF:

CS6/AIS23004303/CVP3

ASSIGNMENT

700D

From:

Date:

Estimated Cost:

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No:

at Workshop m/s

Mova

of

Insured:

Policy No.

SP20037308419

Claims No.

202332007572

Sum Insured:

Excess:

0

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$120K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lump Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SFU 8889T

Yr Regn:

7/1/2019

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Toyota Harrier M Garage C.C 1998

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading

71116

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTEZ B3 GH30J004158

Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / ☒ STD A/Rim or

Tyre Size:

F:

235/55 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7 mm

R/Bal.

7 mm

L/Bal.

7 mm

L/Bal.

7 mm

D.O.A.

16/4/2023

D.O.I.

Survey held at

Desk Top Survey

Des. of Damages: Frt / Rear / ☒ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Nett value \$76,179.

31/5/23

Final fig \$5016 confirmed by email (red 2236.50, 30%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 31/5/23-typist

Days Of Repair: 5

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: Merimen

Lump Sum / I.B.I. (\$ 5016)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

> Back to OneMotoring

D.O.A. : 16/4/2023
Bal. : 5 yrs 8.7 months.
M.V. : \$120,000.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	700D
Vehicle Details	
Vehicle No.:	SFU8889T
Vehicle to be Exported:	No
Intended Deregistration Date:	17 May 2023
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER M GRADE
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	8ARZ148496
Chassis No.:	JTEZB3GH30J004158
Maximum Power Output:	170.0 kW (227 bhp)
Open Market Value:	\$30,806.00
Original Registration Date:	07 Jan 2019
First Registration Date:	07 Jan 2019
Transfer Count:	①
Actual ARF Paid:	\$35,129.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Jan 2029 //
PARF Rebate Amount:	\$26,346.00 17,564
Intended COE Rebate Details	
COE Expiry Date:	06 Jan 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,001.00
COE Rebate Amount:	\$17,475.00
Total Rebate Amount:	\$43,821.00

The information contained herein is correct as at 10 May 2023

OK

19,750
18,940
18,890 (2)



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0086364-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing in New/Used Cars, Hire Purchase & Insurance.



INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2003708419	Date of Loss:	16/04/2023
Vehicle Reg. No.:	SFU8889T	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KEE KOH LEONG		
Make/Model:	TOYOTA HARRIER, 2.0 M GRADE (A)	Vehicle Reg. Date:	07/01/2019
Vehicle Colour:	WHITE	Chassis No:	JTEZB3GH30J004158
Engine No:	8ARZ148496		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	4,845.50
Miscellaneous Items	0.00
Labour	2,330.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	7,175.50
+ GST 8.00% (\$\$)	574.04
Nett Amount (\$\$)	7,749.54

This claim is handled by: BILLY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 26 Apr 2023)**Parts:** M1-SUV TOYOTA HARRIER 2.0 M GRADE (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Mova Automotive Pte Ltd/SFU8889T/26/04/2023 09:43**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT FENDER RH	0.00	0.00	*380.00 F	BUC
2	1		*FRONT FENDER COWLING RH	0.00	0.00	*185.00 F	DIS
3	10		*FRONT FENDER COWLING CLIPS	0.00	0.00	*25.00 F	NEC
4	1		*FRONT SPORT RIM RH	0.00	0.00	*1,680.00 F	CUT
5	1		*FRONT WHEEL HUB RH BEARING	0.00	0.00	*250.00 F	? X NN
6	1		*FRONT KNUCKLE ARM RH	0.00	0.00	*240.00 F	X NN
7	1		*FRONT LOWER ARM RH	0.00	0.00	*220.00 F	X NN
8	1		*FRONT DOOR RH	0.00	0.00	*720.00 F	BUC
9	1		*FRONT DOOR STICKER RH	0.00	0.00	*90.00 F	NEC
10	1		*FRONT DOOR CHROME MOULDING RH	0.00	0.00	*125.00 F	CUT
11	1		*FRONT DOOR PILLAR RH (REPAIR)	0.00	0.00	-	
12	1		*REAR DOOR RH (REPAIR)	0.00	0.00	-	
13	1		*REAR DOOR CHROME MOULDING RH	0.00	0.00	*90.00 F	CUT
14	1		*ROCKER PANEL GARNISH RH	0.00	0.00	*400.00 F	X NN

F=Franchise part.

Sub Total (S\$)

4,405.00

+ Margin on L,N Items 10.00% (S\$)

440.50

Total Parts (S\$)

4,845.50

Mova Automotive Pte Ltd/SFU8889T/26/04/2023 09:43. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK & STRAIGHTEN FRONT DOOR PILLAR RH, REMOVE & REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION	New	600.00 400
2	SPRAY PAINT FRONT FENDER RH, FRONT DOOR PILLAR RH, FRONT DOOR RH, REAR DOOR RH. (PEARL COLOUR)	New	1,400.00 800
3	REMOVE & REPLACE FRONT DOOR INNER TRIM, MECHANISM & CHECK LOCKING SYSTEM	New	60.00 ✓
4	REMOVE & REPLACE FRONT DOOR PILLAR GARNISH RH, COVERING TRIM	New	60.00 ✓
5	REMOVE & REPLACE FRONT UNDER CARRIAGE SUSPENSION RH	New	150.00 ✓
6	COMPUTER WHEEL ALIGNMENT	New	60.00 ✓
Gross Labour Cost (S\$)			2,330.00

Mova Automotive Pte Ltd/SFU8889T/26/04/2023 09:43. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- Not authorise.
- Excess = \$? (TBA)
- Resurvey before paint for P/P repair.
- Survey by Simon Ho (62563561)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
TEL: 6291 2827 FAX: 6296 4390
A/C: 6291 1886 FAX: 6291 7717
UEN No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: MOVA AUTOMOTIVE PTE LTD

BLK 1008 #01-04
BUKIT MERAH LANE 3
SINGAPORE 159722
SFU8889T
BILLY

NO: DL19263525
PAGE: 1
DATE: 17/05/2023
A/C CODE: LDMV315
TERMS: CR
P/O NO: SFU8889T

VEH NO: SFU8889T

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 T53811-48210	1. FR FENDER RH	QB1D15	1	380.00	380.00
2 T53875-48120	2. FENDER LINER FR RH	QBEE11	1	185.00	185.00
3 T90467-07201	3. CLIP,COWLING	DD1A168	10	2.00	20.00
4 T42611-48A10	4. SPORT RIM 18"	QB1HS	1	1,680.00	1,680.00
5 T67001-48150	5. DOOR FR RH	QBEE3	1	720.00	720.00
6 T75921-48050	6. TAPE FR RH	DDS	1	90.00	90.00
7 T75710-48080	7. OUTER MLG FR RH	DUIF22-9	1	125.00	125.00
8 T75730-48070	8. OUTER MLG RR RH	DUIF23-7	1	90.00	90.00
TOTAL QUANTITY			17	TOTAL	SIN 3,290.00
				ADD GST @ 8%	263.20
				GRAND TOTAL	<u>SIN 3,553.20</u>

15 FAN YOONG RD

Print / MT / 17/05/2023 10:12:57 AM

SALESMAN: MT

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E

GOODS RECEIVED BY





合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
TEL: 6291 2827 FAX: 6296 4390
A/C: 6291 1886 FAX: 6291 7717
UEN No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: MOVA AUTOMOTIVE PTE LTD

BLK 1008 #01-04
BUKIT MERAH LANE 3
SINGAPORE 159722
SFU8889T
BILLY

NO: DLI9263773
PAGE: 1
DATE: 24/05/2023
A/C CODE: LDMV315
TERMS: CR
P/O NO: SFU8889T

VEH NO: SFU8889T

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
T75968-48020	TAPE	DDS	1	35.00	35.00
T75929-48020	TAP BLACK OUT LEX	DDS	1	35.00	35.00
TOTAL QUANTITY:			2	TOTAL	SIN 70.00
				ADD GST @ 8%	5.60
				GRAND TOTAL	SIN 75.60

15 FAN YOONG RD

Print / MT / 24/05/2023 10:04:12 AM

SALESMAN: MT

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY



PAYNOW UEN No.
200310923R