




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: HO WINNIE			Ref: CS3/HSB23004306/Wvp3e2 Date: 26/05/2023 Code: HSB	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 2942H	Veh. Inspected	SGE 6060C
	Policy No.		Coverage (\$)	0.00
	Claim No.	S3M04LZA	Excess (\$)	0.00
	Assign From	HO WINNIE	Assign Date	26/04/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HARRIER G	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	JTEKB3GH60J004897	Colour	WHITE
	Odometer	65602 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 R18	BRIDGESTONE	7 mm
	L/H Front Tyre	235/55 R18	BRIDGESTONE	7 mm
	R/H Rear Tyre	235/55 R18	BRIDGESTONE	7 mm
	L/H Rear Tyre	235/55 R18	BRIDGESTONE	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.			
5. General Information				
	Accident Date	24/04/2023	Inspect Date / Time	27/04/2023 (12:15 PM)
	Survey held at	HARMONY MOTOR (AMK) PTE LTD BLK 10 ANG MO KIO IND. PARK 2A #02-12 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	

Report Ref No. CS3/HSB23004306/Wvp3e2

Inspected By

MUHAMMAD AKID BIN MOHAMED KAMAL

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.