

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	SOMPO INSURAN	CE SINGAPORE PL	Ref:	CS/SMO23004307/Acy3e2	
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 D TOWERSINGAPORE 048623	Date:	11/07/2023	
			Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SDJ 8266Y	Veh. Inspected	YN 6584Y	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	CMTD2300933/AGC	Excess (\$)	0.00	
	Assign From	GRACE TEO	Assign Date	26/04/2023	
2.	. Vehicle Particulars & Condition				
	Make & Model	MITSUBISHI CANTER	c.c	2998	
	Engine No.	HIDDEN	Year of Reg.	2014	
	Chassis No.	FEB21EA00964	Colour	WHITE	
	Odometer	198612 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/85 R15	BRIDGESTONE	6 mm	
	L/H Front Tyre	195/85 R15	BRIDGESTONE	6 mm	
	R/H Rear Tyre	195/85 R15	BRIDGESTONE	6 mm	
	L/H Rear Tyre	195/85 R15	BRIDGESTONE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	03/03/2023	Inspection Date	27/04/2023	
	Survey held at	AUTOMOBILE HUB ENTERPRIS	SE		
		1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
		CE TO YOUR INSTRUCTIONS, W	E HAVE NOT AUTHORISE	ED REPAIRS.	
5b.		·	E HAVE NOT AUTHORISE Days of Repair	ED REPAIRS.	