

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 2 May 2023 10:09 AM
To: Ying; Gary Seah
Cc: SUR
Subject: LONPAC-OD GBE 9115T DOA: 20/04/2023

Dear Sir/Madam,

As instructed by our client , please proceed to repair the **insured vehicle GBE 9115T at repair cost on Lump Sum basis, (Excess \$3,100/-).**

“The excess applicable under Section I is \$600.00. An additional excess of \$2,500.00 applied for Young & inexperienced Drivers as the driver has less than 2 years of driving experience.”

If there are any check items or supplementary items please inform our office’s Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)