



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC23004326/Uqy3e2 Date: 19/05/2023 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	GBE 9115T
	Policy No.	Z23V05017110	Coverage (\$)	0.00
	Claim No.	23/23/23/VC05/027305	Excess (\$)	3,100.00
	Assign From	GERALD POH	Assign Date	27/04/2023
2. Vehicle Particulars & Condition				
	Make & Model	ISUZU NHR85 (M)	c.c	2999
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JAANHR85EG7100106	Colour	WHITE
	Odometer	264858 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	DOUBLESTAR	3 mm
	L/H Front Tyre	195 R15	DOUBLESTAR	3 mm
	R/H Rear Tyre	155 R13 (D)	RIVO	6/6 mm
	L/H Rear Tyre	155 R13 (D)	RIVO	6/6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	20/04/2023	Inspection Date	27/04/2023
	Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		
5a. Remarks				
	A) THE MARKET VALUE IS S\$36,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	