

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LIBERTY INSURAN	ICE PTE LTD	R	ef:	CS3/LIP22012084/Twy3e2-1	
	51 CLUB STREET, LIBERTY HOUSES	#03-00 INGAPORE 069428	D	ate:	30/05/2023	
			С	ode:	LIP	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SNC 3117X	Veh. Inspected		SKX 8214R	
	Policy No.	SI22V13412/VPC/R01	Coverage (\$)		0.00	
	Claim No.	IVS22/2058	Excess (\$)		0.00	
	Assign From	ANDY SEAH	Assign Date		27/04/2023	
2. Vehicle Particulars & Condition						
	Make & Model	VOLKSWAGEN GOLF	c.c		1395	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.	WVWZZZAUZFW077599	Colour		SILVER	
	Odometer	108281 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/40Z R18	MICHELIN		5 mm	
	L/H Front Tyre	225/40Z R18	MICHELIN		5 mm	
	R/H Rear Tyre	225/40Z R18	MICHELIN		5 mm	
	L/H Rear Tyre	225/40Z R18	MICHELIN		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	27/11/2022	Inspection Date		05/12/2022	
	Survey held at	LEE LUEW SING MOTORS				
		NO 10 ANG MO KIO INDUSTRIAL PARK 2A #03-10 AMK AUTOPOINT SINGAPORE 568047				
5a.		Remarks				
	A)REGISTRATION DATE: 27 NOV 2014 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					