

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 202332007437 Date: 16<sup>th</sup> June 2023

Our Ref: CS6/AIS23004383/Cwp3m4

## M/s Allianz Insurance Singapore Pte Ltd

79 Robinson Road #09-01 Singapore 068897

Dear Sir / Madam,

## DESKTOP SURVEY OF ACCIDENT VEHICLE SMS 8373S ACCIDENT ON 18/04/2023

We thank you for your instruction on 28/04/2023.

The following vehicle information was recorded:

Registration Number : SMS 8373S

Make & Model : B.M.W. 520I Led Nav Chassis Number : WBAJA12020WW35462

Year of Registration : 2019 Engine Capacity : 1998 cc

- 1. The vehicle sustained damages at the rear o/s portion. (Details see photographs enclosed)
- 2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.