

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	HL ASSURANCE F	PTE LTD		Ref:	CS/HLA23004389/Tvy3	
	11 KEPPEL ROAD #11-01 ABI PLAZA	SINGAPORE 089057		Date:	28/04/2023	
				Code:	HLA	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SMA 724K	Veh. Inspected		CB 8099S	
	Policy No.	MP309231	Coverage (\$)		0.00	
	Claim No.	MPC04104	Excess (\$)		0.00	
	Assign From	GRACE NG	Assign Date		28/04/2023	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	. General Information					
	Accident Date	28/02/2023	Inspection Dat	е	28/04/2023	
	Survey held at	Bedok Motor Engineering Pte Ltd	I			
		30/32 DEFU LANE 9 SINGAPORE 539270				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					