



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CS/LPC23004394/Rwy3m4

Date: 05/06/2023

Code: LPC2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	GBM 2624U
Policy No.	Z23VC05016919	Coverage (\$)	0.00
Claim No.	23/23/23/VC05/027329	Excess (\$)	500.00
Assign From	CHARMAINE KONG	Assign Date	28/04/2023

2. Vehicle Particulars & Condition

Make & Model	BYD ET3	c.c	0
Engine No.	HIDDEN	Year of Reg.	2023
Chassis No.	LC0CE4DB5N0403731	Colour	WHITE
Odometer	1699 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60R16	LING LONG	6 mm
L/H Front Tyre	195/60R16	LING LONG	6 mm
R/H Rear Tyre	195/60R16	LING LONG	6 mm
L/H Rear Tyre	195/60R16	LING LONG	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/04/2023	Inspection Date	03/05/2023
Survey held at	31 CORPORATION ROAD SINGAPORE 649825		
Repairer	DING AUTOMOTIVE PTE LTD		

5a. Remarks

A)THE MARKET VALUE IS S\$122,000.00(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**