

Our Ref : SNC8138C / TP#2031
Your Ref : XE1404B / CC4/III23004405/Kya3

WITHOUT PREJUDICE

Date : 04th July 2023

INDIA INTERNATIONAL INSURANCE PTE LTD

6 Raffles Quay

#22-00

Singapore 048580

Attention: Motor Claims Department

**ACCIDENT INVOLVING SNC8138C & XE1404B ON 26/04/2023
ALONG MARYMOUNT ROAD**

We refer to the above captioned.

We are claiming the below followings:

- Cost of Repair (incl. of GST)	S\$	6,420.54	
- Loss of use	S\$	960.00	(\$120.00 X 08 Days)
- LTA / GIA Search Fee	S\$	26.75	
Grand Total	S\$	<u>7,407.29</u>	

If you have any enquiries, please contact our representative, Mr Joseph at 6481-1522 or email joseph@ow.sg

All payment is to be issued direct to **Optima Werkz Pte Ltd.**

Your prompt attention is most grateful and look forward to your speedy settlement.

Yours faithfully

OPTIMA WERKZ PTE LTD

Encl.

This is a computer generated printout and no signature is required.

Optima Werkz Pte Ltd

10 Ang Mo Kio Industrial Park 2A #01-05, Singapore 568047

Tel (+65) 6481 1522 Fax: (+65) 6481 1011

Co Reg & GST No: 201212455W

TAX INVOICE

To: INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET
#04-00/06-00 IOB BUILDING
SINGAPORE 049711

Tel: 63476100
Fax: 62257743

INV NO. : 322300055
INVOICE DATE : 23/06/2023
REF : TP#2031
VEH NO. : SNC8138C
MAKE : TESLA
CAR MODEL : MODEL 3 SR
CURRENT MILEAGE:
ADVISOR : TING AN
TERMS : COD
MECHANIC :

DESCRIPTION	QTY	UOM	Tax Code	U/P SGD	AMT SGD
REAR DOOR RH	1	PCS	SR	1,048.60	1,048.59
REAR DOOR WEATHERSTRIP RH	1	PCS	SR	97.67	97.67
REAR DOOR INNER TRIM BOARD RH	1	PCS	SR	616.83	616.83
REAR DOOR REGULATOR RH	1	PCS	SR	241.59	241.59
REAR FENDER RH	1	PCS	SR	1,480.37	1,480.37
REAR FENDER QUARTER GLASS RH	1	PCS	SR	308.41	308.41
REAR RIM RH	1	PCS	SR	555.50	555.50
REAR RIM COVER RH	1	PCS	SR	35.98	35.98
REAR DOOR INNER TRIM BOARD CLIPS RH	1	PCS	SR	20.00	20.00
REAR FENDER QUARTER GLASS SEALANT	1	PCS	SR	30.00	30.00
LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.	1	JOB	SR	700.00	700.00
LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT REAR ACCIDENT AREAS & ETC.	1	JOB	SR	500.00	500.00
LABOUR CHARGES TO REMOVE & REPLACE REAR QUARTER GLASS RH & SEALANT. TO EFFECT REPLACE OF REAR FENDER.	1	JOB	SR	60.00	60.00
LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM RH, UPHOLDSTERY CUSHION SET & ETC TO EFFECT REPLACE OF REAR FENDER RH.	1	JOB	SR	120.00	120.00
LABOUR CHARGES TO REMOVE & REPLACE REAR RIM RH.	1	JOB	SR	20.00	20.00
TO WHEEL ALIGNMENT & BALANCING.	1	JOB	SR	60.00	60.00
TO TUFF KOTE & UNDERSEAL MATERIALS.	1	JOB	SR	30.00	30.00
TO CHECK WIRING & ELECTRICAL SYSTEM.	1	JOB	SR	20.00	20.00

Optima Werkz Pte Ltd

10 Ang Mo Kio Industrial Park 2A #01-05, Singapore 568047

Tel: (+65) 6481 1522 Fax: (+65) 6481 1011

Co Reg & GST No: 201212455W

TAX INVOICE

To: INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET
#04-00/06-00 IOB BUILDING
SINGAPORE 049711

Tel: 63476100
Fax: 62257743

INV NO. : 322300055
INVOICE DATE : 23/06/2023
REF : TP#2031
VEH NO. : SNC8138C
MAKE : TESLA
CAR MODEL : MODEL 3 SR
CURRENT MILEAGE:
ADVISOR : TING AN
TERMS : COD
MECHANIC :

DESCRIPTION	QTY	UOM	Tax Code	U/P SGD	AMT SGD
-------------	-----	-----	----------	---------	---------

Remarks: DOA: 26/04/2023 @ 13:50HRS
CLAIMANT: ANG XIULING / ANG BOON HUI
TP VEHICLE: XE1404B

Singapore Dollars: Six Thousand Four Hundred Twenty And Cent Fifty-Four Only

SUB TOTAL	SGD	5,944.94
GST 8.00%	SGD	475.60
TOTAL	SGD	6,420.54
OUTSTANDING	SGD	6,420.54

Tax Legend:

SR - Standard Rated ZR - Zero Rated OS - Out of Scope

Tax	SR
Amount	5,944.94

I/We confirm that I/We incurred the repair costs herein and will observe my/our agreement with the repairs. I/We declare the repairs for above vehicle have been completed to my/our satisfaction.

- 1) New parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of one (1) year or mileage up to 30,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.
- 2) Recon Parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of six (6) months or mileage up to 10,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.
- 3) Goods sold are not refundable/returnable.
- 4) Original Invoice is only valid when the payment is acknowledge receipt by Optima Werkz Pte Ltd. Interest of 2% per month will be charged on any outstanding amount



Opt for a more convenient and quicker way to pay via Bank Transfer or PayNow:
Beneficiary Name: Optima Werkz Pte Ltd
Beneficiary Bank Name: DBS Bank Ltd
Bank Account No.:0039441282
Swift Code: DBSSSGSG
OR
PayNow UEN: 201212455WDB1
Note: Please include your invoice number under the reference section

Customer Acknowledgement

For Optima Werkz Pte Ltd

Customer Name and Signature

Authorised Signature

Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 26 Apr 2023 / 17:20:00

Receipt Date/Time : 26 Apr 2023 / 17:19:49

Tax Invoice/Receipt

Receipt No. : ITNET-00000-230426-003229

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - XE1404B				
As at 26 Apr 2023/13:50:00				
Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - XE1404B			
	Enquiry Fee	24.77	1.98	26.75
	20230426171933755219			
	Sub-Total	24.77	1.98	26.75
	Total Before Rounding	24.77	1.98	26.75
	Rounding Difference			0.00
	Total Amount Payable			26.75
	Paid By			
	cpr88yky		Credit Card	26.75
	Total			26.75
	Cash Change			0.00
	Tendered Amount			26.75
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.


TO WHOM IT MAY CONCERN

AUTHORIZATION TO ACT

I/We(owner) Ang Xiuping ('the third-party claimant') of
(Address) Blk 42 Circuit Road #18-521 S(370042) registered owner of
(Vehicle Number) SNC8138C hereby authorize ('the vehicle repairer workshop')
OPTIMA WERKZ PTE LTD to act for me/us with respect of my/our claim for repair costs and /or
rental and/or loss of use for my/our vehicle number SNC8138C that was
damaged pursuant to the accident which occurred on 26/04/2023 along
Marymount Rd, Singapore involving vehicle number XE1404B.

I/We further authorize the workshop to settle my/our above-mentioned claim in a manner that they
deem fit and the workshop is further authorized to receive full payment in the settlement of my/our
claim with full cheque(s) payment being made in the favor of the workshop.

Dated this 26 day of 04 year 2023.



Signature of Vehicle Registered Owner
Company's stamp (if applicable)