



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23004419/Aqy3m4	
			Date: 14/07/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBB 7230Y	Veh. Inspected	SME 8407C
	Policy No.	D22MTPCVE001563	Coverage (\$)	0.00
	Claim No.	CMTD2301682/AGC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	02/05/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA NOAH HYBRID	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	ZWR800331439	Colour	SILVER
	Odometer	154045 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55R17	NEXEN	6 mm
	L/H Front Tyre	205/55R17	NEXEN	6 mm
	R/H Rear Tyre	205/55R17	NEXEN	6 mm
	L/H Rear Tyre	205/55R17	NEXEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	28/04/2023	Inspection Date	03/05/2023
	Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	