

PAIR DETAILS

Reference

Part Source:	MRM-SG	Version:	1.0 (Last Synchronised: 03 May 2023)
Parts:	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	ComfortDelGro Engineering Pte Ltd/SHD4880J/03/05/2023 13:20		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOTLID <i>Denxx R X</i>	20.00	0.00	*2,609.80 FL
2	1		*BOOTLID EMBLEM <i>NLL -</i>	20.00	0.00	*28.00 FL ✓
3	1		*BOOTLID IONID EMBLEM <i>NLL -</i>	20.00	0.00	*31.30 FL ✓
4	1		*BOOTLID HYBIRD EMBLEM <i>NLL -</i>	20.00	0.00	*24.30 FL ✓
5	1		*REAR BUMPER <i>Sur -</i>	20.00	0.00	*459.40 FL ✓
6	1		*REAR BUMPER MOULDING <i>CSA -</i>	20.00	0.00	*451.25 FL ✓
7	1		*REAR BUMPER REINFORCEMENT <i>1X nn</i>	20.00	0.00	*394.80 FL
8	2		*REAR BUMPER REINFORCEMENT STAY LH/RH <i>3X nn</i>	20.00	0.00	*276.20 FL
9	10		*REAR BUMPER CLIP <i>NLL -</i>	20.00	0.00	*22.00 FL ✓
10	1		*REAR BUMPER LOWER MOULDING <i>Sur -</i>	20.00	0.00	*155.00 FL ✓
11	1		*REAR LOWER CENTRE LOWER COVER <i>1X nn</i>	20.00	0.00	*225.00 FL
12	1		*REAR FOG LAMP <i>1X nn</i>	20.00	0.00	*201.50 FL
13	2		*REAR NUMBER PLATE LAMP LH/RH <i>1X nn</i>	20.00	0.00	*170.60 FL
14	1		*REAR REVERSE SENSOR <i>Family -</i>	0	0.00	*180.00 FS ✓
15	1		*REAR NUMBER PLATE W/HOLDER <i>CSA -</i>	0	0.00	*55.00 FS ✓
16	1		*BOOTLID COMFORT APP STICKER <i>NLL -</i>	0	0.00	*40.00 FS ✓
17	1		*BOOTLID COMFOR LOGO/ TEL NUMBER STICKER <i>NLL -</i>	0	0.00	*60.00 FS ✓

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,384.15
- List Item Discount on L Items (S\$)	1,009.83
Total Parts (S\$)	4,374.32

ComfortDelGro Engineering Pte Ltd/SHD4880J/03/05/2023 13:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

$$P = 1171.25$$

$$20\% = 234.25$$

$$= 937$$

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	PANEL BEATING	New	900.00 700
2	SPRAY PAINTING	New	700.00 500
3	REMOVE/REFIX REVERSE SENSOR	New	60.00 30
4	TUFF COATING	New	60.00 x
5	CHECK LIGHTING/WIRING	New	60.00 30
Gross Labour Cost (S\$)			1,780.00

ComfortDelGro Engineering Pte Ltd/SHD4880J/03/05/2023 13:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

$$\begin{aligned}
 &= 2532 \\
 &2532 - 506.4 \\
 &= 2025.60 \\
 &\approx 2000
 \end{aligned}$$

3 days
L/S
315/23
8 4pm
11km

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: