



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

HSBC LIFE (SINGAPORE) PTE LTD

INV No. AC2303456

10 MARINA BOULEVARD #48-01 MARINA BAY  
FINANCIAL CENTRE TOWER 2  
SINGAPORE 018983  
ATTN: OH VALE

INV Date 31/05/2023  
Reference CS3/HSB23004495/Sqp3m4  
Code HSB

### PROFESSIONAL SERVICE FEE

Vehicle No. SJY 7847C  
Insured Veh. SHA 5300B  
Claim No. S3M04M5T  
Policy No. VFX/P2419138  
Accident Date 29/04/2023  
Inspection Date 03/05/2023

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 04.05.2023)	
Repaired vehicle before return to claimant as per NIMA Protocol (Photo taking + Transport on 09.05.2023)	
<b>Subtotal</b>	<b>100.00</b>
<b>GST (8%)</b>	<b>8.00</b>
<b>Grand Total</b>	<b>108.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

**SML**