

EzLyna (LKKAuto)

From: Ong Hua Yen (Strides Automotive Services Pte Ltd)
<HuaYen.Ong@stridespremier.com.sg>
Sent: Wednesday, 5 July 2023 4:58 PM
To: Admin A; CS A Team
Cc: Chong Fei Yuan (Strides Automotive Services Pte Ltd); Balqish Binte Abdul Halil (Strides Automotive Services Pte Ltd); Tan Wei Teck (Strides Automotive Services Pte Ltd); Karen Chan Siau Chin (Strides Automotive Services Pte Ltd); Foo Chit Yan (Strides Automotive Services Pte Ltd)
Subject: OUR REF:BUS/04/23/5020(AIG) - ACCIDENT ON 13/04/23 INVOLVING SMB3576X AND SJC6500A ALONG Junction of Senja Road and Bukit Panjang Ring Road before BS: 44721 (Opp Jelapang Stn)
Attachments: BUS 04 23 5020 GEARS.pdf; BUS 04 23 5020 INV.pdf; BUS 04 23 5020 SAS.pdf

Dear Sirs,

We claim on behalf of SMRT Buses Ltd, owner of the vehicle registration number SMB3576X. Your client's negligent driving has caused the above accident. As a result, my client has suffered the following losses,

Cost of Repair	\$2,400.00
Loss of Use	\$1,050.00 (3 days x \$350.00)
GEARS search fee	\$1.85
Total	\$3,451.85

We enclose the following documents,

- 1) 1) Repair Invoice
- 2) 2) GIA report
- 3) 3) GEARS Search Fee

We look forward to your confirmation to settle our claims within 15 days from the date of this email. Payment by cheque shall be crossed and made payable to SMRT Buses Ltd.

Thanks & Regards
Hua Yen

DISCLAIMER This electronic mail message and any files transmitted with it are intended exclusively for the individual or entity to which it is addressed. The message, together with any attachment, may contain confidential and/or privileged information. Any unauthorized review, use, printing, saving, copying, disclosure or distribution is strictly prohibited. If you, the reader are not the intended recipient, please do not disclose, disseminate, circulate, copy or use any of the information contained in this email. Please notify us immediately and delete the email and destroy any printed copy.

Customer Code: 3000066

SMRT BUSES LTD

Block Unit

209 KRANJI ROAD
SINGAPORE 739484

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : IV230600024
Date : 07.06.2023
Vehicle No. : SMB3576X
Your Ref No. : BUS/04/23/5020
Our Ref No. : 24118324
Terms : 30 Days

Description	Qty	Unit Cost	Add %	/ (Discount) Amount	Amount
LUMP SUM AMOUNT FOR REPAIR AS PER SURVEYOR'S RECOMMENDATION	1.00				\$ 2,400.00
GRAND TOTAL					\$ 2,400.00

Remark :

Make/Model : ENVIRO 500
Accident Date : 13.04.2023

Payment Instructions

· By Cheque: Crossed and made payable to "Strides
Automotive Services Pte. Ltd." with invoice no. indicated on
the reverse side. No receipt will be issued unless requested.

· By Bank Transfer:

· Account Name : Strides Automotive Services Pte. Ltd.
· Bank Name : DBS Bank Ltd - SGD
· Bank Account No.: 018-008617-4
· Swift Code : DBSSSGSG

Koo Yew Chung
Koo Yew Chung (Jun 7, 2023 14:49 GMT+8)

Authorised Signature
for Strides Automotive Services Pte. Ltd.

INSURER ENQUIRY

Find insurer

Vehicle reg. no.

SJC6500A

Date of Accident

13/04/2023



Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance **AIG Asia Pacific Insurance Pte....**Period of Insurance **26/09/2022 - 25/09/2023**Requested By **BALQISH BINTE ABDUL HALIL (...)**Requested Date **25/04/2023 16:49****Payment details**Request Amount: **S\$1.85**GST Amount: **S\$0.15**Total Amount Due (GST Inclusive): **S\$2****General Insurance Association**

Records Management Centre

GST Registration No: **M400017735**