## Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: 08 Jun 2023 Tan Kah Leong Date:

## **Preliminary Advice**

Insured Vehicle No : SMV7792G

TP Vehicle No : 29/04/2023 : SLC3322T Accident Date Make : KIA FORTE K3 **Assignment Date** : 03/05/2023

Date of Inspection : 03/05/2023 Est. Duration of Repair : 3

Inspection At : THIAM HENG HUAT PTE LTD (SIN MING)

176 SIN MING DRIVE, #05-14

SINGAPORE 575721

## Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,510.60		
Revised Amount	:S\$	1,713.60		
Check Items (Estimated)	:S\$	0.00		
Total	:S\$	1,713.60		
Lump Sum Repair	:S\$	1,350.00		

#### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

#### Remarks

)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kind	lly
	let us have your authorisation.	

	uneconomical to b				

Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to ( X ) consistency check, part prices and labour cost.