



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE PERFORMANCE GST Registration No. 201118055N Company Registration No: 201118055N

ESTIMATE

Wong Yew Hoong
139A LORONG 1A TOA PAYOH #18-44 Singapore
311139

Contact : 98333516

Code : C102066

Date in : 08/05/2023

Vehicle Num. : SKV8761M

Model : TOYOTA WISH 1.8X CVT ABS D/AIRBAG

2WD 5DR

Chassis/Eng# : ZGE206024361/2ZR1589617

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount	
Front Bonnet 11	1	1060.70	1,060.70	X
Front Bonnet Hinges L/R 11	2	63.70	127.40	X
Front Bonnet Insulator 11	1	445.00	445.00	X
Front Bumper 11	1	639.70	639.70	✓
Front Bumper Fog Lamp Cover LH 11	1	92.40	92.40	✓
Front Bumper Inner Sponge 11	1	110.60	110.60	✓
Front Bumper Radiator Grille (Black & Chrome) 11	1	449.30	449.30	X
Front Bumper Reinforcement 11	1	330.60	330.60	X
Front Bumper Side Retainer L/R 11	2	68.10	136.20	120
Front Fender LH 11	1	1071.80	1,071.80	✓
Front Headlamp LH 11	1	1050.10	1,050.10	✓
Front Radiator Lower Grille LH 11	1	50.00	50.00	X
Front Wheelarch LH 11	1	186.80	186.80	✓
Subtotal before discount			5,750.60	
Percentage discount 25%			1,437.65	
Sub-total 1			4,312.95	
front Bumper Clips Set (SN) 11	1	50.00	50.00	30

page 1

no + Authorised
for
work
8/5/23
2/5 # 2900
4 days.



Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg ; enquiry@z-one.com.sg

AUTOMOTIVE PERFORMANCE GST Registration No. 201118055N Company Registration No: 201118055N

Front Fender Inner Shield Clip Set (SN) ^{LH} <i>nel</i>	1	50.00	50.00	30
Subtotal before discount			100.00	
Percentage discount 0%			0.00	
Sub-total 2			100.00	
Parts-total			4,412.95	

LABOUR

Description	Price	
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	150.00	20
Diagnose, replace and/or repair to rectify front portion electrical system for proper functioning.	150.00	X
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,500.00	680
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,700.00	450
To apply anti-rust chemical (Tuff-Kote) on repaired and replaced panel.	180.00	30
Labour Total	3,680.00	
Parts & Labour Total	8,092.95	

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-3219.50
 252
 2-2414.62
 S.N-60
 2-1180
 3654.62
 202
 2927.