



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23004556/Tqy3e2 Date: 30/05/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	GBB 8303P	Veh. Inspected	SNE 8766D
	Policy No.	SI22V07863/VCH/R03	Coverage (\$)	0.00
	Claim No.	IVS23/0650	Excess (\$)	0.00
	Assign From	STEWART LIM	Assign Date	04/05/2023
2. Vehicle Particulars & Condition				
	Make & Model	AUDI A3	c.c	999
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	WAUZZZ8V2H1070457	Colour	BLACK
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
	L/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
	R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm
	L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information				
	Accident Date	29/03/2023	Inspection Date	10/05/2023
	Survey held at	YS Autowerkz #01-03 First East Center Singapore 417868		
5a. Remarks				
	A)REGISTRATION DATE: 29 MAY 2017 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	