



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI23004578/Uny3m4 Date: 09/06/2023 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SNA 9686R	Veh. Inspected	FBQ 4557X
Policy No.	P10840927R00	Coverage (\$)	0.00
Claim No.	C10021011/CH	Excess (\$)	0.00
Assign From	FRAULEINE KHOO	Assign Date	05/05/2023
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA SNIPER T150	c.c	150
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MH3UG0740K0153462	Colour	BLACK
Odometer	-	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	70-90-17	PIRELLI	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	110-70-17	PIRELLI	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	10/03/2023	Inspection Date	05/05/2023
Survey held at	KY AUTO PTE LTD 25 KAKI BUKIT ROAD 4 #05-23 SYNERGY @ KB SINGAPORE 417800		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	